

Five-Year Capital Outlay Master Plan 2013

Including

Facility Assessment Report

Index

Lake Superior State University Five-Year Capital Outlay Master Plan and Facility Assessment Report

Executive Summary

- I. University Mission and Vision and Statements
- **II.** Instructional Programming
- III. Staffing and Enrollment
- **IV.** Facility Assessment
- V. Implementation Plan
- VI. General Issues Concerning Capital Improvement Plan
- VII. Campus Improvement Requirements
- VIII. Master Plan Summary

Appendix - Facility Assessment Report

Executive Summary

Lake Superior State University Five-Year Capital Outlay Master Plan and

Facility Assessment Report

This document provides an overview of the University's Mission, Instructional Programming, Staffing and Enrollment, and a detailed Facility Assessment Report.

The University boasts a wonderful location on a scenic bluff overlooking the St. Marys River and close to Lake Superior in one of the most scenic parts of the State of Michigan. The campus has a unique mixture of historic buildings from Fort Brady and more modern. Lake Superior State University has carefully tended its physical plant and infrastructure despite limited funds available for that purpose.

This document summarizes the University's mission, enrollments and physical plant needs. Included in this document are the University's principles for campus development, a summary of its major infrastructure and deferred maintenance needs. Finally, this document includes a detailed listing of the capital expenditure and deferred maintenance needs for each of LSSU's campus buildings.

I. Lake Superior State University Mission

Following is the current Mission and Vision Statements for LSSU. These were approved by the Board of Trustees on November 11, 2011.

Mission Statement

Our mission at Lake Superior State University is to help students develop their full potential. We launch students on paths to rewarding careers and productive, satisfying lives. We serve the regional, state, national and global communities by contributing to the growth, dissemination, and application of knowledge.

Vision Statement

Our programs grow and evolve in ways that keep our graduates at the cutting edge of technological and societal advances. As such, we will be viewed by our constituents as:

- The preferred regional choice for students who seek a quality education which provides a competitive edge in an evolving job market.
- An institution where relevant concepts are taught by quality faculty, and are paired with practical real-world experience to provide a well-rounded education.

- An institution which capitalizes on its location to instill graduates with an understanding
 of environmental issues and an overarching desire to be responsible stewards of the
 environment.
- A University that is highly student centered and empowers all students to realize their highest individual potential.

II. Instructional Programming

A. Describe existing academic programs and projected programming changes during the next five years, in so far as academic programs are affected by specific structural considerations.

Courses of study at the University range from traditional, liberal arts programs to engineering and nursing. LSSU offers associate and baccalaureate degrees and a Masters of Arts in Curriculum and Instruction. The current programmatic array will be further enhanced by the addition of new programs that take advantage of the University's international setting and the region's natural resources and climate. Existing programs that are showing growth will receive additional resources as appropriate; programs showing extended no growth will be revamped or eliminated.

All existing programs will undergo a rigorous assessment regarding academic outcomes and cost efficiencies; new programs will be evaluated with an eye towards the needs of the State, additional revenue potential and resource availability.

B. *Identify the unique characteristics of each institution's academic mission:*

The student body comprises 50% male, 50% female, 89% Michigan residents, 7% non resident foreign and 12% minority students, 8% of which are Native Americans, reflecting the diversity makeup of Michigan's Upper Peninsula. Student surveys have indicated that students are drawn to LSSU for its small campus atmosphere and unique programs.

The University's location plays an important role in its academic mission. The region's abundant natural resources, international setting, rich heritage and large Native American population provide ample opportunity for the institution to design and offer academic programs appropriate for its mission.

Lake Superior State University currently serves students in its region and beyond by offering twenty-four associate's degree programs, seventy-three undergraduate programs, six certificate programs, one post baccalaureate program, and one master's degree program.

Courses of study at the University range from traditional, liberal arts programs to engineering, nursing and fire science. LSSU offers associate and baccalaureate degrees and a Masters of Arts in Curriculum and Instruction. Current areas of study include:

Lake Superior State University Five-Year Master Plan 2013

Accounting

Applied Geographic Information Science

Athletic Training

Biology

Business Administration

Business Administration - Entrepreneurship

Business Administration - International Business

Business Administration - Management

Business Administration - Marketing

Chemical Technology

Chemistry

Communication

Computer and Mathematical Sciences

Computer Engineering

Computer Information Systems

Computer Networking

Computer Science

Conservation Biology

Conservation Leadership

Criminal Justice

Criminal Justice - Corrections

Criminal Justice - Criminalistics

Criminal Justice - Generalist

Criminal Justice - Homeland Security

Criminal Justice - Law Enforcement

Criminal Justice - Loss Control

Criminal Justice - Public Safety

Curriculum and Instruction

Early Childhood Education

Electrical Engineering

Electrical Engineering Technology

Elementary Teaching

Elementary Education: Special Education-Learning Disabilities

Engineering Management

English Language and Literature

Environmental Chemistry

Environmental Health

Environmental Management

Environmental Science

Exercise Science

Finance and Economics

Fine Arts Studies

Fire Science

Fire Science - Engineering Technology

Lake Superior State University Five-Year Master Plan 2013

Fire Science - Generalist

Fire Science - Hazardous Materials

Fish Health

Fisheries Wildlife Management

Forensic Chemistry

French Studies

Geology

Health Care Provider

Health/Fitness Specialist

History

Individualized Studies

Industrial Technology

Integrated Science

Internet/Network Specialist

Language Arts

Liberal Arts

Liberal Studies

Literature

Literature - Creative Writing

Manufacturing Engineering Technology

Marine Technology

Mathematics

Mechanical Engineering

Medical Laboratory Science

Natural Resources Technology

Nursing

Paramedic Technology

Paramedic Training

Parks and Recreation

Personal Computer Specialist

Political Science

Practical Nursing

Psychology

Secondary Teaching

Social Science

Social Studies

Social Work

Sociology -General

Sociology-Social Services

Spanish

Sport and Recreation Management

Substance Abuse Prevention and Treatment

Technical Accounting

Successful partnerships with charter schools, community colleges, other Michigan public universities, and other area agencies and institutions have created positive educational and economic impacts. The University continues to reach out to area residents, businesses, governments, social agencies and public and private institutions to develop new and more effective activities and programs.

III. Staffing and Enrollment

A. Current full and part-time student enrollment levels and Access

This fall's enrollment has seen a 7% decrease in degree seeking students with an 11% decrease in new freshmen. This year's new transfer students saw a 19% decrease. The fall to fall retention of full-time degree seeking new freshmen held at 68%. The University's five year, academic year unduplicated head count average is just under 3,100 students, graduate and undergraduate.

This fall 16% of our enrollment is part time, 93% of course enrollments are on the home campus, 1% at regional sites, 4% off campus or at other campuses, and 2% delivered through distance education. Most courses are delivered in a classroom or lab setting with an increasing number provided through the internet or by tape delay.

B. Projected Enrollment Patterns for Next Five Years

The University's Strategic Planning and Budget Committee, a committee of Shared Governance, and the President's Cabinet are presently reviewing its five year enrollment growth strategy in conjunction with the implementation of the university's strategic plan. Included in the strategy will be an increase in articulation agreements with other colleges in Michigan and Ontario, collaboration with both public and private sector entities, and an active involvement in the eastern upper peninsula's economic development strategic planning.

Historically, as a small regional public university, LSSU's focus has been on serving the needs of its region. Hence, to date, distance learning initiatives have not been a priority. However, as part of its growth strategy, the University plans to add more quality online programs, investigating various distance learning technologies for their academic appropriateness and cost efficiency.

Lake Superior State University has been recognized by GI Jobs Magazine as a Military Friendly School which honors the 15% of the country's colleges and universities that do the most to welcome military veterans and enhance their experience as students. We expect increased interest in our programs from veterans and their families.

The latest U.S. Bureau of Labor Statistics indicate that occupations that typically need some type of postsecondary education for entry are projected to grow the fastest during the 2010-2020 decade.

The University is committed to growing both on the home campus, in the regional centers and through new online programs. Action plans continue to be formulated to support increased enrollment and retention.

C. Evaluation of Enrollment Patterns Over the Last Five Years

As the state of Michigan's economy has continued to be bleak over the last few years, cuts to higher education funding from the State have been necessitated. Due to its size, economy of scale and student demographics, Lake Superior State University has been adversely impacted by the cuts to its State appropriations and by the removal of the separate reimbursements for the Michigan Indian Tuition Waiver.

Programs that have shown the greatest growth are in the sciences (Biology, Environmental Programs, Fisheries and Wildlife), Fire Science, Exercise Science, and Athletic Training. Some growth was noted in the programs of Business, Criminal Justice, and Engineering. As an indication of the University's commitment to meeting the needs of the State, programs have been added or expanded in Teacher Education (Special Education), Homeland Security, and Nursing.

D. Student: Faculty and Student: Administrator Ratios

The University's current student/full-time faculty ratio is 18 to 1. Maintaining a low student to faculty ratio is considered a major strength of the University, emphasizing as it currently does undergraduate education. Additionally, our students are in classes with qualified faculty, not graduate or teaching assistants. The student/administrative ratio is 18 to 1.

E. Future Staffing Needs

Decisions about future staffing will be driven by academic programs demonstrating sustained enrollment growth and by providing, or enhancing, services that directly benefit students. The University is currently reviewing its staffing levels across campus as well as revenue enhancing areas, such as the Foundation.

D. Average Class Sizes

Consistent with its mission emphasizing undergraduate education, more than 76% of the main campus course lecture sections enrolling fewer than 30 students. More than 200 laboratory classes have fewer than 20 students per class and the campus provided computer to student ratio is a low 12 to 1.

IV. Facility Assessment

A comprehensive building-by-building Facility Assessment Report addressing the information requested is included as an appendix to this document. This assessment report is regularly updated. This plan identifies the considerable needed repairs and improvements for the next five-

years, reflecting the substantial deferred maintenance associated with a campus that includes many aging, historical buildings.

The Physical Plant strives to maintain campus while making energy conscious decisions. A campus wide energy plan is being developed. Steam traps are inspected annually to ensure proper function. CSD-1 testing is performed annually on all boilers to ensure proper combustion efficiencies are maintained. Johnson Controls completed an energy audit of the major campus buildings in 2008. All Phase Electric completed a lighting audit of major campus buildings in 2009. Energy projects are completed as funding is available.

Utilization of academic space is reviewed each semester to ensure existing spaces are fully utilized. This data also provides important information needed for assessing future campus space requirements. The chart below summarizes this falls utilization rates in lecture rooms, laboratories, and other building academic spaces. Rates are looked at for 45 hour weeks (M-F, 8am-5pm) and 65 hour weeks (M-F, 8am-9pm).

University Space Utilization						
Building	Average % Use Lecture Rooms 45 hr Week	Average % Use Lecture Rooms 65 hr Week	Average % Use Labs 45 hr Week	Average % Use Labs 65 hr Week	Average % Use Total Building 45 hr Week	Average % Use Total Building 65 hr Week
Art Center	59%	48%	21%	18%	40%	33%
Brown Hall	18%	12%	NA	NA	18%	12%
Center for Applied Science and Engineering Technology	67%	67%	22%	18%	40%	32%
Crawford Hall of Science	67%	55%	28%	21%	39%	30%
KJS Library	64%	51%	16%	13%	40%	32%
Norris Center	66%	50%	18%	15%	29%	22%
Campus Wide	57%	45%	21%	17%	34%	27%

Over the last few years the University has been successful in some infrastructure repairs/replacements. The University completed a \$85,000 project replacing the siding, fascia and soffit on our Townhouses. The Quarterdeck Dining Facility was renovated. The new equipment and serving areas allow for greater variety of services. East Hall was renovated and reopened to house the Little Lakers Kinder College. The roof was replaced over the Norris Center Pool. Several porches were fixed on the historic row houses. Erie Hall received kitchen upgrades. New carpet was laid in several facilities and new "green" floor and carpet cleaning equipment was purchased which should make the carpets last longer.

Other improvements include:

Information Technology Infrastructure:

Installed a dedicated generator for campus datacenter.

Enhanced existing campus WiFi, increasing the number of total number of wireless access points by 50% to address areas on campus with weak wireless signal.

Continued implementation of PC replacement strategy, when fully implemented no computer on campus will be over 5 years old (currently in 3rd year)

Upgraded network hardware (switches/routers/etc), replacing aging network gear.

University Physical Infrastructure

Made safety and ADA repairs, upgrades and improvements including restroom retrofits; door, stairway and tread repairs; required signage; and ventilation improvements.

Began replacement of deteriorated sidewalks, parking lots and roadways.

Renovated and reopened East Hall to house the Little Lakers Kinder College.

Student Residential Facilities

Completed a project to replace siding, fascia and on the Townhouses.

Refurbished some aspects of Osborn Hall and Brady Hall including roof repairs, painting, new flooring and general refurbishment.

Erie Hall kitchens and front porches were renovated.

Renovated student areas in the Cisler Center.

Upgraded Campus Dining Facilities

The Quarterdeck Dining Facility was renovated. Upgraded equipment and serving areas have allowed for expanded services. The seating areas received new furniture and finishes to give the area greater functionality and a new look. The Galley also received some upgrades.

Secured Professional Facility Planning Assistance

Secured professional assistance for architectural, engineering, landscaping and other facility planning and analysis.

Substantially Upgraded Landscaping and Campus Appearance

A major campus landscaping project has been successfully undertaken to restore the natural beauty of the campus after years of neglect. This includes removing dead trees, installing local stone fixtures and locally-relevant plants and trees. Much of this effort has been funded by donations of specimens and materials and use of already-on-board campus facilities personnel. Campus landscaping is a continual process with projects coordinated with sidewalk replacement.

Planning Process

Beginning in 2010, the Infrastructure Development Committee (IDC) of the Shared Governance system replaced the previously named Capital Improvement Plan Committee. The committee consists of the Provost, Vice President of Student Affairs, Vice President for Finance, Director of Physical Plant, Director of the Foundation, One Dean selected by the Provost's Council, two faculty members selected by the faculty association, two staff members selected by the support group association, two elected administrative professionals and one student elected by Student Government.

The IDC is charged with (1) reviewing and recommending updates to the campus master plan on a periodic basis, (2) evaluating and making recommendations concerning campus facilities that may need renovation or repairs as well as the need for new facilities or modified use of existing facilities, (3) providing recommendations about renovation and repairs to campus facilities and infrastructure, including major technology components, (4) reviewing all of these needs in light of the long range goals of the University, and (5) communicating its deliberations and findings to the President and the University community. The IDC reports to the President through the Provost.

The Shared Governance system allows broader participation in the decision making process and helps to facilitate the collaboration of new ideas and innovations positioning the University to move forward.

V. Implementation Plan

A. Prioritization of Major Capital Projects for which State Funding Has Been Requested -

LSSU's major capital project request includes a building for the School of Business approved for planning by the State of Michigan. The State has advised they are not accepting new capital outlay requests in fiscal year 2013.

B. Estimate of LSSU's Current Deferred Maintenance Backlog -

Current deferred maintenance backlog for general fund facilities is currently estimated at \$9,891,000and \$9,388,000for auxiliary facilities. The IDC will assist in prioritizing and

Lake Superior State University Five-Year Master Plan 2013

continually re-evaluating our most important needs, taking into account the serious shortage of funds for our purposes and declining support from the State of Michigan.

C. Status of On-Going Projects -

Lake Superior State University is currently planning its School of Business Building under PA 329 of 2010. The Program Statement and Schematic Design submittal has been reviewed by the Department of Technology, Management & Budget (DTMB) Facilities Administration Design and Construction Division and was recommended for submission to the Joint Capital Outlay Committee (JCOS) for approval. If approved through JCOS for inclusion in the next capital outlay appropriations act and passed, construction will begin January 2014.

D. Rate of Return Anticipated on Planned Expenditures -

Most savings are expected by renovating buildings that meets Michigan's "Green Initiatives" including renovations that will be LEED certifiable. Revenue increases will also be generated by attracting students to a state of the art facility which currently does not exist.

E. Alternatives to New Infrastructure -

The School of Business building will be a renovation of a historical building.

F. Maintenance Schedule for Major Maintenance Items in Excess of \$1 Million -

The University is planning a privately funded renovation of the Norris Center athletic complex beginning in the spring of 2013. The donor specific renovation is estimated to be \$4.3 million. No other major renovation or maintenance projects in excess of \$1 million are planned.

G. Non-Routine Budgeted Maintenance -

The University has budgeted \$85,400 in our minor construction line item and \$300,000 in a Plant Fund for general non-routine maintenance. Additionally, the housing and food service auxiliaries will contribute approximately \$300,000 to a reserve and replacement fund.

VI. General Issues in Capital Improvements

This planning document is organized to first present background information on the University's current focus and status. It then reviews the intended use of various areas of the campus and presents specific capital needs of the University. The final section summarizes the recommendations for action.

Campus Environment and Design Issues

The lack of continuous, comprehensive facility and space planning has left the campus with several major issues which now must be addressed. Some will be addressed in the discussion of individual development zones below. However, the overall campus design calls for several actions to ensure long term viability and maturation.

<u>First</u> is a commitment to a landscape plan that ensures the perpetuation of site lines and interior pathways to provide pleasing views, pedestrian usability, and efficient, environmentally friendly year-round maintenance. Landscape planning, for the purposes of this plan is inclusive of trees, shrubs, ground cover, signage, structure siting and lighting.

<u>Second</u>, the University's pedestrian pathway, vehicle pathway and parking lot plans need extensive consideration. All of the conditions for landscape apply to the parking plan. In addition, the safety and transit interests of pedestrians and the parking needs of specific populations need to be reviewed. Consideration must extend to the interests and needs of students, staff, faculty, visitors and event attendees.

A <u>third</u> issue of overall design concern is the improvement of the campus entry points. They need to be improved to present a better image, easier access and exit and more direct access to services being sought by visitors to the campus. Examples of current issues needing attention include: the campus entrance is not well defined; visitors approaching the campus in vehicles are not always effectively directed to locations they may be seeking and the pedestrian/vehicle interfaces at the campus entries are dangerous to both motorists and pedestrians.

Among the guiding principles for overall campus design are:


- 1. Establish building sites and travel routes so that the campus maintains a pleasant, pedestrian-friendly environment while enhancing connectivity between and among facilities.
- 2. Development of a landscape plan that ties the campus to the natural Eastern Upper Peninsula environment while providing secure, cost-efficient year round maintenance.
- 3. Creation of a campus entry that invites visitors into the campus and provides direct access to the services most often sought by visitors (visitor information, Admissions, Business Office, Financial Aid and Registration).
- 4. Design campus-wide signage to guide vehicular and pedestrian campus users more effectively.
- 5. Base all campus planning on an environmental landscape orientation that preserves views within and from the campus. The physical plan of the campus must be aesthetically,

Lake Superior State University Five-Year Master Plan 2013

operationally and environmentally sound. A central "greenway" must be consistent throughout the campus.

Development Zones

"Development zones" define areas within which facilities or other campus features will be primarily located. They include current use as well as sites for future buildings or space use. The value of maintaining currently defined zone use will be continually reviewed by the IDC in consultation with faculty, staff and students to review to determine whether zone uses should be altered or reconsidered.



Development Zone 1 – Academic Facilities


No.	Building
1	Townhouses
2	Fine and Performing Arts Center
3	Walker Cisler Center
4	Center for Applied Science and Engineering Technology
5	Ontario Hall
6	Huron Hall
7	Laker Hall
8	Chippewa Hall
9	Eskoonwid Endaad (Native American Center)
10	Erie Hall
11	University Row Storage Building
12	Hillside House (Admissions)
13	President's House
14	Alumni House
15	Marquette Hall
16	Neveu Hall
17	Moloney Hall
18	Canusa Hall (Barnes & Noble Bookstore at LSSU)
19	Fletcher Center for Student Services
20	Administration Building
21	Kenneth Shouldice Library
22	Brown Hall
23	Gate House
24	Central Heating Plant
25	The Student Village
26	Osborn Hall
27	Brady Hall
28	Crawford Hall of Science
29	South Hall
30	Michigan Hall
31	East Hall (Little Lakers Kinder College)
32	Easterday House
33	Ryan House
34	Counseling Services
35	Edna M. Youngs LSSU Health Care Center
36	Student Activity Center
37	James Norris Physical Education Center & Taffy Abel Arena
38	Leno A. Pianosi Maintenance Center
39	Storage Building
40	Storage Building

Developmental Zone 1 – Academic Facilities

This zone is primarily located on the northern side of the main campus, with one academic building on the south side of Easterday Avenue. It comprises the Kenneth Shouldice Library, the Crawford Hall of Science, South Hall, the Center for Applied Sciences and Engineering and Technology, and the Arts Center on the north, and the Norris Center on the south side of Easterday Avenue. The designation of this zone is intended to define the academic core of the University.

The following key design and physical planning points shall be used to further develop Zone 1:

- Locate future academic facilities within this zone.
- Maintain a compact connection between all University academic facilities.
- Design improvements and secure traffic control changes to improve pedestrian safety at the Easterday/Meridian intersection and at campus interior roadway crossings.
- Design all academic facilities with information technology infrastructure that is applicable to current pedagogical requirements and adaptable to foreseeable technology developments.
- Develop a schedule for upgrading and/or replacing classroom furniture in academic facilities.
- Include student use areas within all academic facilities (lounge/study areas).
- Strive for maximum energy efficiency in new facility designs or rehabilitation of existing facilities.



Development Zone 2 – Administrative and Student Support Facilities

No.	Building
1	Townhouses
2	Fine and Performing Arts Center
3	Walker Cisler Center
4	Center for Applied Science and Engineering Technology
5	Ontario Hall
6	Huron Hall
7	Laker Hall
8	Chippewa Hall
9	Eskoonwid Endaad (Native American Center)
10	Erie Hall
11	University Row Storage Building
12	Hillside House (Admissions)
13	President's House
14	Alumni House
15	Marquette Hall
16	Neveu Hall
17	Moloney Hall
18	Canusa Hall (Barnes & Noble Bookstore at LSSU)
19	Fletcher Center for Student Services
20	Administration Building
21	Kenneth Shouldice Library
22	Brown Hall
23	Gate House
24	Central Heating Plant
25	The Student Village
26	Osbom Hall
27	Brady Hall
28	Crawford Hall of Science
29	South Hall
30	Michigan Hall
31	East Hall (Little Lakers Kinder College)
32	Easterday House
33	Ryan House
34	Counseling Services
35	Edna M. Youngs LSSU Health Care Center
36	Student Activity Center
37	James Norris Physical Education Center & Taffy Abel Arena
38	Leno A. Pianosi Maintenance Center
39	Storage Building
40	Storage Building

Developmental Zone 2 – Administrative and Student Support Facilities

This zone defines the locations for Administrative and student support facilities. These functions include University central Administrative and operational support functions as well as central student support functions. The zone designation derives from consideration of the needs of:


- (1) potential students and visitors;
- (2) current students; and
- (3) instructional support and operational functions of the University.

Defining this zone centered on how critical services to students could be more efficiently and effectively located. One conclusion was that the campus does not have a well-defined entrance. Another was that the services needed by both new and continuing students (Admissions, Registration, Business Office, Financial Aid, Housing Office, Student Life Office, Counseling Services and Student Health Care Center) need to be at a central location, or in close proximity to each other and near a visitor parking area. A third conclusion was that the University and its students would benefit from a revitalized more student oriented Cisler Center.

Further discussion resulted in recognition that the development of a new entrance and re-location of all the student support offices to a central location near the entrance is a long-term goal. However, the potential of developing the Cisler Center into a Student Union which would add more Student Government offices, and, possibly, other services to those already housed there is a near term possibility. In addition to the services noted, other desirable amenities for this building have been adapted which include lounges, study space, coffee and refreshment centers and other comfortable yet functional spaces for student use. These improvements to the Cisler Center provide a central location on campus for commuter students as well as a convenient "stop-off" location for on-campus students.

The following key planning and design points will guide development within this zone:

- Provide for barrier free access to all Administration and student support facilities.
- Provide for easy access to University Administration and student services offices with short term parking spaces for visitors.



No.	Building
1	Townhouses
2	Fine and Performing Arts Center
3	Walker Cisler Center
4	Center for Applied Science and Engineering Technology
5	Ontario Hall
6	Huron Hall
7	Laker Hall
8	Chippewa Hall
9	Eskoonwid Endaad (Native American Center)
10	Erie Hall
11	University Row Storage Building
12	Hillside House (Admissions)
13	President's House
14	Alumni House
15	Marquette Hall
16	Neveu Hall
17	Moloney Hall
18	Canusa Hall (Barnes & Noble Bookstore at LSSU)
19	Fletcher Center for Student Services
20	Administration Building
21	Kenneth Shouldice Library
22	Brown Hall
23	Gate House
24	Central Heating Plant
25	The Student Village
26	Osborn Hall
27	Brady Hall
28	Crawford Hall of Science
29	South Hall
30	Michigan Hall
31	East Hall (Little Lakers Kinder College)
32	Easterday House
33	Ryan House
34	Counseling Services
35	Edna M. Youngs LSSU Health Care Center
36	Student Activity Center
37	James Norris Physical Education Center & Taffy Abel Arena
38	Leno A. Pianosi Maintenance Center
39	Storage Building
40	Storage Building


Development Zone 3 – Campus Residences

Development Zone 3 – Campus Residences

Student residential facilities will be located within the areas as shown. The residence zones closest to the center of campus are intended for freshmen and sophomore residence facilities. These locations are in close proximity to the main University dining facility and other student life services. The residential areas further from the campus core are intended to accommodate facilities for upper division students or, potentially, staff, faculty or visiting student populations. The Officers' Row residence facilities are intended for specially designated resident use.

The following key planning and design points will guide development of the Campus Residence Zone:

- Develop a schedule to refurbish and renovate all residence facilities on a regular basis to meet contemporary student interests and needs. Among the standards to be set for all residence hall improvements are:
 - o Common areas: security; communications; conducive furnishings and color schemes; recreational spaces; and storage areas.
 - o Personal accommodations: furnishings; electronic and information technology, color, drapery and floor coverings; appropriate lighting; physical environment; toilet/bath facilities; storage; and accessibility.
- Develop plans for upper division student residential facility.
- Create a landscape plan surrounding student residences that provides for secure and accommodating year-round pedestrian pathways, recreation space and green space.



Development Zone 4 – Athletic Facilities


No.	Building
1	Townhouses
2	Fine and Performing Arts Center
3	Walker Cisler Center
4	Center for Applied Science and Engineering Technology
5	Ontario Hall
6	Huron Hall
7	Laker Hall
8	Chippewa Hall
9	Eskoonwid Endaad (Native American Center)
10	Erie Hall
11	University Row Storage Building
12	Hillside House (Admissions)
13	President's House
14	Alumni House
15	Marquette Hall
16	Neveu Hall
17	Moloney Hall
18	Canusa Hall (Barnes & Noble Bookstore at LSSU)
19	Fletcher Center for Student Services
20	Administration Building
21	Kenneth Shouldice Library
22	Brown Hall
23	Gate House
24	Central Heating Plant
25	The Student Village
26	Osbom Hall
27	Brady Hall
28	Crawford Hall of Science
29	South Hall
30	Michigan Hall
31	East Hall (Little Lakers Kinder College)
32	Easterday House
33	Ryan House
34	Counseling Services
35	Edna M. Youngs LSSU Health Care Center
36	Student Activity Center
37	James Norris Physical Education Center & Taffy Abel Arena
38	Leno A. Pianosi Maintenance Center
39	Storage Building
40	Storage Building

Development Zone 4 – Athletic Facilities

This zone includes the Norris Center, Student Activity Center, outdoor tennis courts, Blair Hasting property and an open recreation field north of the Student Activity Center.

The Blair Hasting property south of the Student Activity Center presents an opportunity to develop a recreational area and playing fields. Hiking trails, outdoor ice rink and fields to accommodate intramural soccer, softball and football could be located in this space. The following key planning and design points will guide development of the campus athletic facilities zone:

- Secure external funding to improve Norris Center facilities;
- Develop a better and clearer entrance to the Norris Center, integrating the building complex;
- Secure student interest in changes to existing facilities or for additional recreation facility development.
- Develop a schedule for upgrading and refurbishing existing facilities; and
- Describe the safety, cost effectiveness and "green" requirements to be included and maintained at all recreational locations and facilities.



Development 2	Zone 5 – Mai	ntenance and	Heating	Facilities
----------------------	--------------	--------------	---------	-------------------

Γ.		T
L	lo.	Building
	1	Townhouses
	2	Fine and Performing Arts Center
	3	Walker Cisler Center
	4	Center for Applied Science and Engineering Technology
	5	Ontario Hall
	6	Huron Hall
	7	Laker Hall
	8	Chippewa Hall
	9	Eskoonwid Endaad (Native American Center)
1	10	Erie Hall
1	11	University Row Storage Building
1	12	Hillside House (Admissions)
1	13	President's House
1	14	Alumni House
1	15	Marquette Hall
1	16	Neveu Hall
1	17	Moloney Hall
1	18	Canusa Hall (Barnes & Noble Bookstore at LSSU)
1	19	Fletcher Center for Student Services
2	20	Administration Building
2	21	Kenneth Shouldice Library
2	22	Brown Hall
2	23	Gate House
2	24	Central Heating Plant
2	25	The Student Village
2	26	Osborn Hall
2	27	Brady Hall
2	28	Crawford Hall of Science
2	29	South Hall
3	30	Michigan Hall
3	31	East Hall (Little Lakers Kinder College)
3	32	Easterday House
3	33	Ryan House
3	34	Counseling Services
3	35	Edna M. Youngs LSSU Health Care Center
3	36	Student Activity Center
3	37	James Norris Physical Education Center & Taffy Abel Arena
3	38	Leno A. Pianosi Maintenance Center
3	39	Storage Building
4	40	Storage Building

Development Zone 5 – Maintenance and Heating Facilities

This Zone is split between the Heating plant located at the south west corner of the main campus and the central physical plant offices, shops, warehouses, motor pool and receiving located on the south campus. The following key planning and design points will guide development of the campus maintenance projects and heating facilities.

- Maintain current rosters of deferred maintenance projects and costs;
- Develop interior storage for large University equipment and vehicles in order to extend life cycle; and
- Maintain high standard of grounds and building exterior maintenance around all central maintenance facilities, etc.

Circulation Issues

The movement of pedestrians and vehicles to and within campus presents several different problems for resolution. The matter is complicated by regulations and traffic issues leading to or immediately adjacent to the University.

Vehicular Movement

A major goal of this and future facility planning efforts is to limit vehicular traffic in the core campus area. The intent is to move vehicular traffic from the interior of the main campus to the perimeter of the campus. Moving forward with this concept will create a safer pedestrian environment. However, it will require revamping or relocating some of the existing parking and related access roads.

The current main entrance off Easterday Avenue will be maintained for the foreseeable future. However, substantial improvements to this entrance must be made to create a clearly defined and inviting gateway to the campus. Alternatives exist, but each presents major problems due to traffic and site line problems which would have major negative impacts on pedestrians.

The existing Easterday/Meridian intersection should be improved, however, and the City of Sault Ste. Marie is willing to work with the University in the planning of these improvements. The establishment of turn lanes and changes or additions to traffic signaling will help eliminate the vehicular accidents and close calls involving pedestrians at this location.

Presently, circulation of vehicles from the current main entrance through campus must be maintained in order to access the visitor's parking lot (D Lot) at the Administration Building, Lot K at the Arts Center, and Lot E behind the Cisler Student and Conference Center and the Center for Applied Sciences Building. This road is the only vehicular route through the main campus. At this point the City of Sault Ste. Marie has requested that the University limit traffic from the

perimeter city streets on the north side of campus. Honoring this request requires that the current entrance be maintained as the main access route for vehicles to the central campus. Consequently, this roadway carries a heavy passenger vehicle, delivery vehicle and large truck traffic load. The current entrances on the east side of the campus (Ryan Street and Sheridan Drive) should be maintained. However, the traffic there should be limited and monitored in order to honor the privacy of the homes surrounding the campus.

Pedestrian Movement

Pedestrian movement around the main campus faces three specific problems. The first is the need for substantial replacement and repair of sidewalks through the campus. Second, due to the large number of students going to the Norris Center and the Norris parking lots from the central campus, a continuous interface between student foot traffic and vehicles traveling Easterday Avenue is created. The third pedestrian issue is the lack of adequate signage and traffic control on the campus. Each of these issues is more specifically addressed below. In general, however, keeping future development of academic buildings grouped within the academic development zone will help maintain the needed close proximity for students and faculty moving between classes.

The existing sidewalk inventory is in immediate need of upgrading. Many sidewalks are broken, have different levels where they join creating trip hazards or are underwater at rainy or snowy times. Another problem is the narrowness of the many existing walks. Because they are narrow they create problems for efficient snow removal.

The crossing at Easterday Avenue is a major, continuous safety concern. Students currently cross Easterday at three main locations. The largest number cross at the intersection of Easterday and Meridian where a traffic signal helps control the traffic flow. However, many pedestrians cross between the Norris Center and parking Lot O and between parking Lot L and Crawford Hall where no signals exist. The City of Sault Ste. Marie is willing to work with the University in developing a better traffic/pedestrian signal at the Easterday and Meridian intersection and will consider adjusting the speed limit through that area. The control of the pedestrians at locations with no crossing signals is a matter that has to be addressed cooperatively by the City and the University Public Safety Department.

The last pedestrian issue needing attention is signage. Implicit in this consideration are the review and updating of University traffic and parking regulations. Most importantly, though, signage clearly marking pedestrian crossings, indicating pedestrian right of way, identifying campus building and facilities, and giving clear directions to campus locations is required.

VI. Campus Improvement Requirements

The Physical Plant Department of the University annually updates its assessment of deferred maintenance for all University buildings. The current estimated cost of addressing all of the

existing deficiencies is \$9,891,000 for general fund facilities and \$9,388,000 for auxiliary fund facilities. Facility specific cost estimates are included in the appendix.

Academic Facilities

The currently defined Academic Development Zone provides enough space to accommodate academic facility needs for the immediate future. The inventory of classrooms and laboratories on campus, while currently reasonable in number, requires many upgrades and improvements. The University has a request before the State of Michigan for construction funding to renovate South Hall to be used primarily by the School of Business. Completion of this project will provide much more effective classrooms and enable more efficient scheduling of the entire instructional facility inventory to accommodate the demand for classrooms. However, improvements to other structures are needed to meet barrier free accessibility standards and bring the facilities up to date in terms of technology, general function and appearance. Classrooms must be upgraded to support current and emerging pedagogy. These changes need to provide for group work assignments, emerging classroom instructional technology and a wireless computer environment for both student and faculty interests. A companion need for classroom upgrades is a schedule or process for the replacement of classroom furniture.

Space for future expansion is available within the defined academic zone. Maintaining the academic core on the north side of Easterday Avenue provides ample infill growth opportunities. For new facilities as well as the refurbishment and upgrading of existing facilities, the general exterior design standard for the University will continue to be design, materials and finishes that match or closely align with the historical appearance of the campus.

The Norris Center on the south campus provides the classroom space for the Recreation, Exercise Science and Criminal Justice and Fire Science programs. This facility is dated and in need of both cosmetic and structural updates.

The new addition of the donated building for housing the Aquatics Research Laboratory and Educational Center needs substantial renovations before the facility can be re-located from its current temporary building to the donated building.

Infrastructure

The electrical, mechanical, water and other infrastructure systems at the University are, except for those within new facilities, quite old and outdated. They have been well maintained over the years and, for the most part, remain usable. They do, however, require frequent repair.

Priority infrastructure issues include:

• The University has made substantial progress in upgrading its Information Technology capability and in moving to a mostly wireless campus. However, more work is needed in

the classrooms to assure that all have the appropriate infrastructure for our pedagogical needs.

There are many safety, access and deferred maintenance issues needing attention at the
University. Walkways, roadways, railings, entry ways, drainage and stairways are in need
of attention. Similarly, there is a backlog of repair requirements for the roofs and
exteriors of campus buildings that need attention before major winter or water damage
occurs. The Facility Assessment Report in the appendix describes the majority of these
projects.

Student Services

As plans for new or reconfigured space use in the Cisler Center are made, consideration needs to be given to locating all of the University services required by students in a central location. These services include admissions, registration, financial aid, business office, residential housing and food services; and possibly student health services. Reconfiguration of the Cisler Center as a student union/center is a possible location. However, having all of these services in a location that can be easily accessed by both off-campus visitors and campus students is important. As a new campus entry and new facilities are considered, a central, easily accessible location for these operations should be considered.

Housing Facilities

The current location of residential facilities meets the goal of easy student accessibility of academic and support facilities. However, each of the current residential facilities requires updating and many major renovations or replacements to meet current student interests. These improvements are needed not only to better accommodate current students. They are required if LSSU is to be in a more competitive position with other universities for student enrollment. Renovation of the existing facilities must be scheduled during the summer months or at other times that will avoid displacing students.

The Appendix describes the majority of the required repairs. However, that section does not address the refurbishment needs of these facilities. Refurbishment is a major need to maintain student satisfaction of University residence facilities. Staff members from Student Life, Housing and Residential Life and Plant Services are continually working on plans that will address the upgrading of these facilities.

Food Service Facilities

Food facilities are currently offered in four locations at LSSU: the Quarterdeck, the major food service facility for resident students; the Galley, a lunch hour grill in the lower level of the Cisler Center; Cappuccino Corner, a sandwich and coffee room in the Library; and Café ala Cart, a coffee and snack facility in Crawford Hall. Through a partnership arrangement with the University's food service management firm, SODEXO, Café ala Carte was added in January,

2004 and the Cappuccino Corner was updated in the summer of 2004. The Quarterdeck dining facility was renovated in the summer of 2012. Upgraded equipment and serving areas have allowed for expanded services. The seating areas received new furniture and finishes to give the area greater functionality and a new look. The Galley also received some upgrades in the summer of 2012. The upgrades, funded by SODEXO, are based, in part, on student interests expressed in focus groups and research on student food interests.

VII. Master Plan Summary

The University is blessed with a beautiful campus with a wonderful location overlooking the St. Marys River and close to Lake Superior. The campus is a delightful mixture of historic and newer buildings. However, in order to maintain the integrity of the campus and to advance its mission, considerable attention is needed to infrastructure issues.

Although there are many needs, the following reflect the University's current priorities and interests for campus development:

- Maintain the request to the State of Michigan for construction funding to renovate South Hall for the School of Business;
- Identify funding for the rehabilitation of the donated building to house the Aquatics Research Laboratory and Educational Center;
- Continue upgrading the University's technology infrastructure to deliver Internet and network connections required by the students, faculty and staff, including the provision of wireless technology in specific areas of the campus.
- Improve and upgrade the most critical campus infrastructure needs including safety and
 access improvements, the main electrical service, the central heating plant, the most
 damaged walkways and roadways, and the highest priority roof replacements and
 building exteriors.
- Plan needed improvements to campus residential facilities. The existing residential
 facilities need substantial upgrading, refurbishment or replacement. The University's
 housing facilities are in particular need of attention.
- Develop campus signage that provides effective directional orientation for all campus constituents and promotes a "pedestrian first" environment.
- Plan for the development of a Student Union at the Cisler Center. The planning should include the incorporation of an improved restaurant facility, lounges, study areas and student activity offices.

- Maintain the historical architectural look of the old Fort Brady complex of historically
 important buildings. The scale and design of new buildings should be integrated with the
 historical presence of the existing structures. It is suggested that Hillside House, which is
 currently being used by the Admissions Office, be converted into a student residential
 facility.
- Make the best use of academic spaces and maximize academic seat utilization.
- Invest in facilities important to student recruitment and retention, such as the Student Activity Center.
- Facilitate building linkages and develop a more pedestrian-oriented campus.
- Base all campus planning on an environmental landscape orientation that preserves views within and from the campus and builds on the natural look and feel of the campus. The physical plan of the campus must be aesthetically, operationally and environmentally sound. A central "greenway" must be consistent throughout the campus.
- Include environmental compatibility and economy of operation in all capital planning and improvement decisions.
- Maintain regular meetings of the IDC and annual updates of the University's Five-Year Master Plan.

Appendix



Five-Year Facility Assessment 2013




Five-Year Facility Assessment 2013

Table of Contents

Campus Map	i	Marquette Hall	51
Administration Building	1	Meridian Storage Bldg	53
Alumni House	3	Michigan Hall	55
Aquatic Research Laboratory	5	Moloney Hall	57
Arts Center	7	Neveu Hall	59
Barnes & Noble at LSSU	9	Norris Center	61
Brady Hall	11	Ontario Hall	63
Brown Hall	13	Osborn Hall	65
CASET Building	15	Pianosi Maintenance Building	67
Central Heating Plant	17	President's House	69
Chippewa Hall	19	Row Housing Storage Bldg	71
Cisler Center	21	Ryan House	73
Crawford Hall of Science	23	South Hall	75
East Hall	25	Student Activity Center	77
Easterday House	27	Student Village	79
Erie Hall	29	Townhouses	81
Eskoonwid Endaad	31	Youngs House	83
Fire Science Bldg	33	Infrastructure	85
Fletcher Center	35	2012-13 Summary	87
Gate House	37	2013-14 Summary	88
Health Care Center	39	2014-15 Summary	89
Hillside House	41	2015-16 Summary	90
Housing Storage Bldg	43	2016-17 Summary	91
Huron Hall	45	2017-18 Summary	92
KJS Library	47		
Lakor Hall	10		

Many capital improvement items have been deferred to 2014 and beyond with hopes that funds will become available.



Parking Key

- A Commuter/Faculty-Staff
- B Commuter/Faculty-Staff
- C Osborn and Village Residents
- D Visitor Parking (register at Public Safety)
- E Senior Commuter/Faculty-Staff
- University Row Residents and Staff
- G Easterday and Ryan House Residents
- H Brady Hall Residents
- J Faculty-Staff T Townhouse Residents
 K Parking as designated for Barnes & Noble, Faculty-Staff and Ingiliary Staff and Ingili
- L Osborn and Village Residents
- M Motor Pool
- N Commuter Parking
- O Osborn and Village Residents' Day Use: No Overnight Parking
- S Moloney and Neveu Hall Residents

 - NO PARKING ON ANY UNIVERSITY DRIVE

www.lssu.edu

36. Student Activity Center (SAC), Robert Arbuckle

13. President's Residence 33. Ryan House

1. Townhouses

25. The Village

Public Safety: 906-635-2100 Admissions: 906-635-2231 Switchboard: 906-632-6841

Departments (Alphabetic	al)
DEPARTMENTS BL	DG #
Academic ComputingAcademic Records	4
Administrative Offices	20
Administrative Computing	4
Admissions Alumni Relations	
Arena - Taffy Abel	37
Athletics	37
Audio-Visual	21
Biological Sciences Barnes & Noble at LSSU (UPS and USPS)	18
Black Box Theatre	2
Business Operations	19
Café a la Carté	28
Campus Life	3
Career Services	21
Cashier	19
Catering Chemistry & Physical Sciences	28
Compass (student newspaper)	3
Communication Studies	
Counseling Services	34
Concessions	
Criminal Justice, Fire Science & EMS	37
Disability Services	
Education Engineering & Engineering Technology	22
Inglish & Language Studies	2
inancial Aidinancial Aidinancial Aidinancial Aid	19 2
oundation	14
ood Services	3
Gallery, ArtGallery, L.F. Noyes Collection	21
Galley, Grill 155°	3
GraphicsGleason Environmental Institute	
Gymnasium - Bud Cooper	
lealth CARE Center	
lonors Programluman Resources	
lousing & Residential Life	3
D Officeteractive Television	3
Cemp Mineral Museum	28
earning Center	
ibraryittle Lakers Kinder Collge	21
Aailroom Aathematics & Computer Science Jative American & Student Diversity Center .	20
Nathematics & Computer Science	4
lursing	28
Payroll Peacock Cove	
Planetarium - Ben Long	
President	20
Product Development Center (PDC) Public Relations	4
Public Safety	20
Purchasing Quarterdeck Dining Hall	20
Recreation & Exercise facilities 36	& 37
Recreation Studies & Exercise Science	37
RegistrarResidence Halls/Living Learning Communitie	
Brady Hall (freshman men)	27
Chippewa Hall (LLC row house-Eng. Club) . Easterday Hall (row house-upper class)	8
Erie Hall (LLC row house-CJ & FS)	10
Huron Hall (LLC row house-Chemistry Club)6
Laker Hall (LLC row house-Fish & Wildlife C Moloney Hall (apts-upper class)	17
Neveu Hall (ants-upper class)	16
Ontario Hall (LLC row house-Honors) Osborn Hall (freshman women)	5 26
Ryan House (upper class)	33
Townhouses (upper class)	1
The Village (sophomores)(Senter, Chelberg, Kemp & Young)	
Risk Management	20
Scheduling	
Student Government	3
Student Service Counter Testing Services	19
Jpward Bound	27
ice President for Academic Affairs & Provos	.20
/ice President for Enrollment Services /ice President for Finance	20
ice President for Student Affairs	3
VLSO Radio Station	3



Administration Building

Description

Primary Use: University Administration Offices Constructed: 1920 original with 1946 addition Building Area: 17,247 square feet on 3 floors

Building Usage

Gross Area: 100% 17, 247 square feet Net Assignable Area: 11,728 square feet 68.0% Circulation Area: 2,932 square feet 17.0% Custodial Area: 259 square feet 1.5% Mechanical Area: 604 square feet 3.5% Construction Area: 1,725 square feet 10.0%

Mandated Facility Standards: N/A

Functionality: N/A

Replacement Value: (2012 valuation) \$2,694,681

Facility Condition Index: 38% (Poor)



Utility System Infrastructure: The entire building interior needs to be remodeled. The mechanical and electrical systems are old and inefficient. The space configuration does not meet the current needs and the building does not meet ADA standards for plumbing or multi-floor access. The building is listed on the Register of National Historic Places.

Administration Building Page 2

Five -Year Capital Improvement Plan

Year	Description	Estimate
2012 - 13	Replace 1st floor carpet	\$7,500
2012 - 13	Repair vent stack - sewer system	\$5,000
2012 - 13	Lighting retrofit	\$20,000
2013 - 14	Rebuild dormers and new windows	\$20,000
2013 - 14	Repair floor sags	\$10,000
2013 - 14	Restore & paint exterior stairs	\$6,000
2013 - 14	Clean, tuck-point and seal coat exterior	\$45,000
2014 - 15	Metering utilities	\$22,500
2014 - 15	Dewater basement/seal basement	\$150,000
2014 - 15	Renovate men's restroom	\$15,000
2015 - 16	Renovate women's restroom	\$15,000
2015 - 16	New fire alarm system	\$36,000
2015 - 16	Replace interior doors	\$33,000
2016 - 17	Install ADA ramp & door opener system	\$40,000
2016 - 17	Renovate HVAC system & add	\$460,000
	HW heating	
2017 - 18	Elevator	\$150,000
	TOTAL	\$1,035,000



ALUMNI HOUSE

Description

Primary Use: Alumni Offices

Constructed: 1920

Building Area: 4,462 square feet on 3 floors

Building Usage

Gross Area: 4,462 square feet 100% Net Assignable Area: 3,034 square feet 68.0% Circulation Area: 759 square feet 17.0% Custodial Area: 67 square feet 1.5% Mechanical Area: 154 square feet 3.5% Construction Area: 446 square feet 10.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$929,527

Facility Condition Index: 52% (Poor)



Utility System Infrastructure:

Building infrastructure is in fair condition with no major problems. However, this facility is circa 1920 and needs extensive work to be brought into the 21st century.

Alumni House

Five -Year Capital Improvement Plan

Year	Description	Estimate
2012 - 13	Replace roof	\$36,000
2013 - 14	Clean/abate lead & asbestos in basement	\$7,000
2013 - 14	Install ADA door hardware	\$5,000
2014 - 15	Replace windows	\$50,000
2014 - 15	Replace electrical panels	\$7,000
2014 - 15	Replace carpeting	\$15,000
2015 - 16	Repair/replace interior ceilings	\$8,000
2015 - 16	Renovate both entrances	\$30,000
2015 - 16	New fire alarm system	\$25,000
2016 - 17	Renovate sanitary system	\$20,000
2016 - 17	Clean, tuck-point and seal coat exterior	\$45,000
2017 - 18	Install new HVAC system with steam to HW heating conversion	\$200,000
2017 - 18	Install ADA access ramp	\$36,000
-	TOTAL	\$484,000



AQUATIC RESEARCH LABORATORY

Description

Primary Use: Education and research

Constructed: 1902

Building Area: 16,350 square feet on 3 floors

Building Usage

Gross Area: 16,350 square feet 100%
Net Assignable Area: 14,225 square feet 87.0%
Circulation Area: 1,602 square feet 9.8%
Custodial Area: 260 square feet 1.6%
Mechanical Area: 260 square feet 1.6%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$306,744

Facility Condition Index: +100% (Poor)



Utility System Infrastructure: The entire building interior needs to be remodeled. The mechanical and electrical systems are old and inefficient. The space configuration does not meet the current needs. The building does not meet ADA standards for plumbing or multi-floor access. The building is listed with the National Historic Civil Engineering Landmarks.

Aquatic Research Lab Page 6

Five -Year Capital Improvement Plan

Awaiting Funding for Complete Renovation

Year	Description	Estimate
	Complete Renovation	\$15,000,000
	(Not included in summaries)	
_	TOTAL	\$15,000,000



ARTS CENTER

Description

Primary Use: Auditorium, Classrooms &

Support Spaces

Constructed: Construction Completed 2004 Building Area: 63,791 square feet on 3 floors

Building Usage

Gross Area:	63,791 square feet	100.0%
Net Assignable Area:	35,723 square feet	56.0%
Circulation Area:	12,120 square feet	19.0%
Custodial Area:	128 square fæt	0.2%
Mechanical Area:	8,038 square feet	12.6%
Construction Area:	7,783 square feet	12.2%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$15,936,540

Facility Condition Index: 0.22% (Good)



Utility System Infrastructure

This facility was opened in August of 2005 for classes and performances. The infrastructure is new and in excellent condition.

Arts Center Page 8

	Year	Description	Estimate
	2012 - 13	Resurface stage wood floor	\$10,000
	2014 - 15	Add lighting to auditorium	\$17,000
	2016 - 17	Add additional electrical power to	\$8,000
		sound and lighting booth	
	•	TOTAL	\$35,000



BARNES & NOBLE AT LSSU

Description

Primary Use: Campus Bookstore

Constructed: 1967

Building Area: 15,091 square feet on 2 floors

Building Usage

Gross Area: 15,091 square feet 100% Net Assignable Area: 10,262 square feet 68.0% Circulation Area: 2,565 square feet 17.0% Custodial Area: 226 square feet 1.5% Mechanical Area: 528 square feet 3.5% Construction Area: 1,509 square feet 10.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$2,524,743

Facility Condition Index: 5% (Fair)



Utility System Infrastructure:

Building infrastructure is in fair condition with no major problems.

Barnes & Noble at LSSU Page 10

Year	Description	Estimate
2014 - 15	Replace fascia & soffit	\$15,000
2014 - 15	Dewater basement	\$5,000
2015 - 16	Install new fire alarm system	\$31,000
2016 - 17	Replace windows throughout building	\$40,000
2017 - 18	New electrical feed and panel	\$40,000
	TOTAL	\$131,000



BRADY HALL

Description

Primary Use: Student Residence

Constructed: 1939

Building Area: 48,896 square feet on 3 floors


Building Usage

Gross Area: 48,896 square feet 100% Net Assignable Area: 39,117 square feet 80.0% Circulation Area: 3,423 square feet 7.0% Custodial Area: 489 square feet 1.0% Mechanical Area: 2.0% 978 square feet Construction Area: 4,890 square feet 10.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$11,713,962

Facility Condition Index: 12% (Poor)



Utility System Infrastructure:

Building infrastructure is in good condition with no major problems. However, the building is circa 1939 and needs renovation work to be brought into the 21st century.

Brady Hall Page 12

Year	Description	Estimate
2012 - 13	Repair water infiltration into basement	\$15,000
2012 - 13	Clean and seal porches	\$25,000
2013 - 14	Replace DHW recirc. lines,valves & pumps	\$20,000
2013 - 14	Replace SE exterior doors	\$6,000
2013 - 14	Electric re-heat elements for bathroom exhaust units	\$6,000
2013 - 14	Add card access entry system	\$25,000
2014 - 15	Renovate plumbing system	\$12,000
2014 - 15	Renovate bathrooms & showers	\$80,000
2014 - 15	Add exterior building drainage to south & east sides	\$20,000
2014 - 15	Replace flooring in basement hallways & areas	\$20,000
2014 - 15	Recore all locking hardware	\$10,000
2014 - 15	Clean, tuck-point and seal coat exterior	\$75,000
2015 - 16	Replace flat roof	\$160,000
2015 - 16	Re-shingle roof	\$50,000
2016 - 17	Add HVAC system to all floors	\$475,000
2016 - 17	Add fire suppression system	\$200,000
2017 - 18	ADA access to 1st floor	\$40,000
2017 - 18	Elevator	\$150,000
	TOTAL	\$1,389,000



BROWN HALL

Description

Primary Use: Administrative Offices

Constructed: 1920 original with 1965 renovation Building Area: 4,768 square feet on 3 floors

Building Usage

Gross Area: 4,768 square feet 100% Net Assignable Area: 3,242 square feet 68.0% Circulation Area: 811 square feet 17.0% Custodial Area: 72 square feet 1.5% Mechanical Area: 167 square feet 3.5% Construction Area: 477 square feet 10.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$993,273

Facility Condition Index: 23% (Poor)



Utility System Infrastructure:

The building is in poor condition. This building is circa 1920 and in need of a major renovation to bring it into the 21st century.

Brown Hall Page 14

Year	Description	Estimate
2012 - 13	Paint exterior trim	\$5,000
2012 - 13	Renovation for Graphics Department	\$90,000
2013 - 14	New fire alarm system	\$18,000
2014 - 15	Install ADA door hardware	\$5,000
2015 - 16	Install metering	\$14,000
2015 - 16	Renovate sanitary system	\$12,000
2016 - 17	Add new domestic water service	\$10,000
2017 - 18	Clean, tuck-point and seal exterior	\$60,000
2017 - 18	Install ADA access ramp	\$10,000
-	TOTAL	\$224,000



CASET BUILDING

Description

Primary Use: Classrooms and Support Spaces

Constructed: 1981

Building Area: 82,055 square feet on 3 floors


Building Usage

Gross Area: 82,055 square feet 100% Net Assignable Area: 59,080 square feet 72.0% 12,308 square feet Circulation Area: 15.0% Custodial Area: 1,231 square feet 1.5% Mechanical Area: 2,051 square feet 2.5% Construction Area: 7,385 square feet 9.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$19,503,216

Facility Condition Index: 4% (Good)



Utility System Infrastructure:

Building is in generally good condition.

CASET Building Page 16

Year	Description	Estimate
2012 - 13	Lighting upgrade in shops	\$15,000
2012 - 13	Renovate Education Department Offices	\$15,000
2012 - 13	Renovate Rm 102 into smart classroom	\$50,000
2013 - 14	Update elevator	\$80,000
2013 - 14	Repair brick and & drip edge east side	\$5,000
2014 - 15	Install overhead door in welding area	\$54,000
2014 - 15	Re-core and change all locking hardware to ADA	\$48,000
2015 - 16	Replace 13 exterior doors	\$40,000
2015 - 16	Overhead lift for foundry/crane machine shop	\$30,000
2016 - 17	HVAC renovation and controls	\$80,000
2016 - 17	Restroom piping retrofit for ADA compliance	\$12,000
2017 - 18	Replace and renovate cooling system	\$250,000
	TOTAL	\$679,000



CENTRAL HEATING PLANT

Description

Primary Use: Campus Steam Generating Plant Constructed: Original Construction, 1969 Building Area: 10,376 square feet on 2 floors

Building Usage

Gross Area: 10,376 square feet 100.0% Net Assignable Area: 7,056 square feet 68.0% Circulation Area: 1,764 square feet 17.0% Custodial Area: 156 square feet 1.5% Mechanical Area: 3.5% 363 square feet Construction Area: 10.0% 1,038 square feet

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$4,053,591

Facility Condition Index: 8% (Fair)



Utility System Infrastructure:

The building and boiler systems are in good condition.

Central Heating Plant Page 18

Year	Description	Estimate
2012 - 13	Design stone fascia replacement	\$15,000
2013 - 14	Replace stone fascia	\$158,000
2015 - 16	Replace underground storage tanks	\$100,000
2016 - 17	Complete steam tunnel repairs	\$50,000
	TOTAL	\$323,000



CHIPPEWA HALL

Description

Primary Use: Student Residence

Constructed: 1920 with 1996 renovation Building Area: 7,752 square feet on 3 floors

Building Usage

Gross Area:	7,752 square feet	100%
Net Assignable Area:	6,202 square feet	80.0%
Circulation Area:	543 square feet	7.0%
Custodial Area:	78 square feet	1.0%
Mechanical Area:	155 square feet	2.0%
Construction Area:	775 square feet	10.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$1,614,902

Facility Condition Index: 9% (Fair)



Utility System Infrastructure

Building infrastructure is in fair condition with no major problems.

Chippewa Hall Page 20

Year	Description	Estimate
2012 - 13	Replace carpet on 2nd floor	\$5,000
2013 - 14	Install 2 new boilers	\$18,000
2013 - 14	Replace basement windows	\$6,000
2014 - 15	Clean/abate basements	\$9,000
2014 - 15	Re-core all locking hardware	\$5,000
2015 - 16	Clean, tuck-point and seal exterior	\$45,000
2015 - 16	Install card access entry system	\$10,000
2016 - 17	Repair fascia and soffit	\$10,000
2016 - 17	Replace interior & exterior cellar doors	\$7,000
2017 - 18	Install ADA accessibility ramp	\$35,000
	TOTAL	\$150,000



CISLER CENTER

Description

Primary Use: Food Service, Classrooms,

Convention & Hospitality Center

Constructed: 1973 with 1994 addition Building Area: 86,685 square feet on 2 floors

Building Usage

Gross Area: 100.0% 86,685 square feet 68.0% Net Assignable Area: 58,946 square feet 17.0% Circulation Area: 14,736 square feet Custodial Area: 1,300 square feet 1.5% Mechanical Area: 3,304 square feet 3.5% Construction Area: 10.0% 8,669 square feet

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$13,978,637

Facility Condition Index: 6% (Fair)



Utility System Infrastructure:

The building infrastructure is in generally good condition.

Cisier Center Page 22

Year	Description	Estimate
2012 - 13	Galley snack bar ceiling replacement	\$18,000
2012 - 13	Tilt fryer installation	\$5,000
2012 - 13	Phase 1- landscape improvements	\$30,000
2013 - 14	Ballroom floor - refinish portion and	\$35,000
	install carpet in remaining area	
2013 - 14	Phase 1 - Replace single pane windows	\$15,000
2013 - 14	Modify fire alarm system	\$15,000
2013 - 14	Install washing machine and dryer	\$5,000
2013 - 14	Replace electrical panels	\$7,000
2014 - 15	Phase 2 -Replace single pane windows	\$15,000
2014 - 15	Phase 2- landscape improvements	\$15,000
2015 - 16	Phase 3 - Replace single pane windows	\$15,000
2015 - 16	Phase II remodeling	\$50,000
2015 - 16	Remodel guest rooms	\$25,000
2015 - 16	Phase 3- landscape improvements	\$15,000
2016 - 17	Phase III remodeling	\$30,000
2016 - 17	Replace EPDM roofing system	\$120,000
2017 - 18	Phase IV remodel	\$30,000
2017 - 18	New cooling coil for HVAC west end	\$35,000
2017 - 18	Re-core and replace all locking	\$30,000
	hardware for ADA	
2017 - 18	Emergency generator system	\$300,000
	TOTAL	\$810,000



CRAWFORD HALL OF SCIENCE

Description

Primary Use: Chemistry, Biology, Forestry, Fire Science, Zoology, & Nursing Science

Constructed: 1964 with 1974 & 2000 additions Building Area: 121,599 square feet on 3 floors


Building Usage

Gross Area: 121,599 square feet 100.0% Net Assignable Area: 82,687 square feet 68.0% 20,672 square feet 17.0% Circulation Area: 1.5% Custodial Area: 1,824 square feet Mechanical Area: 4,256 square feet 3.5% 12,160 square feet 10.0% Construction Area:

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$60,923,621

Facility Condition Index: 0.2% (Good)



Utility System Infrastructure:

The entire facility is in good condition.

Crawford Hall of Science Page 24

Year	Description	Estimate
2013 - 14	Add exterior drainage on west side of building	\$15,000
2014 - 15	Water-proof wall between Room 109 and 110	\$10,000
2015 - 16	Renovate HVAC intake	\$40,000
2016 - 17	HVAC Renovations - Add space sensors for climate control	\$60,000
	TOTAL	\$125,000



EAST HALL

Description

Primary Use: Little Lakers Kinder College Constructed: Original Construction, 1920

Renovated in 2012

Building Area: 3,939 square feet on 2 floors

Building Usage

Gross Area: 100.0% 3,939 square feet Net Assignable Area: 2,769 square feet 68.0% 17.0% Circulation Area: 670 square feet **Custodial Area:** 59 square feet 1.5% Mechanical Area: 138 square feet 3.5% Construction Area: 394 square feet 10.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$820,577

Facility Condition Index: 3% (Good)



Utility System Infrastructure:

Building completely renovated in 2012. Building infrastructure is in good condition.

East Hall Page 26

Year	Description	Estimate
2015 - 16	Replace shingle roof	\$20,000
•	TOTAL	\$20,000



EASTERDAY HOUSE

Description

Primary Use: Student Residence

Constructed: 1920

Building Area: 3,500 square feet on 3 floors

Building Usage

Gross Area: 3,500 square feet 100.0% Net Assignable Area: 2,800 square feet 80.0% Circulation Area: 245 square feet 7.0% Custodial Area: 35 square feet 1.0% Mechanical Area: 70 square feet 2.0% Construction Area: 350 square feet 10.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$729,123

Facility Condition Index: 72% (Poor)



Utility System Infrastructure

Building infrastructure is in poor condition, as the building interior needs to be remodeled to conform to all applicable codes.

Easterday House Page 28

Year	Description	Estimate
2013 - 14	Re-core all locking hardware	\$5,000
2013 - 14	Re-shingle roof	\$30,000
2014 - 15	Install card access entry system	\$10,000
2014 - 15	Clean and abate basement	\$10,000
2015 - 16	Replace decks and porches	\$12,000
2015 - 16	Clean, tuck-point and seal exterior	\$35,000
2016 - 17	Renovate interior	\$300,000
2016 - 17	Replace heating system	\$60,000
2017 - 18	Replace basement windows	\$5,000
2017 - 18	Install ADA accessibility ramps	\$65,000
	TOTAL	\$532,000



ERIE HALL

Description

Primary Use: Student Residence

Constructed: Original Construction, 1901 Building Area: 8,766 square feet on 3 floors

Building Usage

Gross Area: 8,766 square feet 100.0% Net Assignable Area: 7,021 square feet 80.0% Circulation Area: 7.0% 614 square feet Custodial Area: 88 square feet 1.0% Mechanical Area: 2.0% 176 square feet Construction Area: 10.0% 878 square feet

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$1,826,141

Facility Condition Index: 30% (Poor)



Utility System Infrastructure:

Building infrastructure is in poor condition as the building interior needs to be remodeled to conform to current codes. This building is circa 1901 and needs many renovations and improvements.

Erie Hall

Year	Description	Estimate
2012 - 13	Repair chimneys	\$8,000
2013 - 14	Replace basement entrances	\$13,000
2013 - 14	Clean/abate basements	\$10,000
2014 - 15	Clean, tuck-point and seal exterior	\$46,000
2014 - 15	Repair soffit and fascia	\$10,000
2015 - 16	Install card access entry system	\$10,000
2015 - 16	Complete renovation	\$400,000
2016 - 17	Install ADA accessibility ramp	\$35,000
2017 - 18	Re-core all locking hardware	\$5,000
-	TOTAL	\$537,000



ESKOONWID ENDAAD

Description

Primary Use: Campus Native American Center Constructed: Original Construction, 1920 Building Area: 5,078 square feet on 3 floors

Building Usage

Gross Area: 5,078 square feet 100.0% Net Assignable Area: 3,529 square feet 69.5% 863 square feet Circulation Area: 17.0% **Custodial Area:** 76 square feet 1.5% Mechanical Area: 2.0% 102 square feet Construction Area: 10.0% 508 square feet

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$1,057,853

Facility Condition Index: 22% (Poor)



Utility System Infrastructure:

Building infrastructure is in fair condition with no major problems.

Eskoonwid Endaad Page 32

Year	Description	Estimate
2012 - 13	Repair chimneys	\$5,000
2012 - 13	Repair decks and porches	\$8,000
2013 - 14	Replace basement entrance	\$7,000
2013 - 14	Clean/abate basement	\$5,000
2014 - 15	New fire alarm system	\$20,000
2014 - 15	Install ADA door hardware	\$5,000
2014 - 15	Repair soffit and fascia	\$10,000
2015 - 16	Replace basement windows	\$6,000
2015 - 16	Clean, tuck-point and seal exterior	\$45,000
2016 - 17	Convert heat system from steam to HW	\$55,000
2017 - 18	Add fire suppression system	\$25,000
2017 - 18	Install ADA accessibility ramp	\$35,000
	TOTAL	\$226,000



FIRE SCIENCE BUILDING

Description

Primary Use: Laboratory Constructed: 1998

Building Area: 800 square feet on 2 floors

Building Usage

Gross Area: 800 square feet 100% Net Assignable Area: 800 square feet 100%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$116,660

Facility Condition Index: 25% (Poor)



Utility System Infrastructure:

Building infrastructure is in fair condition with no major problems.

Fire Science Building Page 34

Year	Description	Estimate
2015 - 16	100 ft by 75 ft concrete pad for fire equipment	\$30,000
	TOTAL	\$30,000



FLETCHER CENTER

Description

Primary Use: Registrar, Financial Aid & Other

Student Services

Constructed: 1936 original w/ 1977 renovation Building Area: 14,540 square feet on 3 floors

Building Usage

Gross Area: 14,540 square feet 100.0% Net Assignable Area: 9,887 square feet 68.0% Circulation Area: 17.0% 2,472 square feet 1.5% **Custodial Area:** 218 square feet Mechanical Area: 3.5% 509 square feet 1,454 square feet 10.0% Construction Area:

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$3,028,984

Facility Condition Index: 18% (Poor)



Utility System Infrastructure:

Building infrastructure is in generally fair condition. Many needs of the building are due to circa 1936 construction and the changing needs of campus.

Fletcher Center Page 36

Year	Description	Estimate
2012 - 13	Replace carpet in south side of building	\$10,000
2013 - 14	Remove old boiler system and abate	\$6,000
2013 - 14	Modify existing fire alarm system	\$8,000
2013 - 14	Metering	\$21,000
2014 - 15	Repair basement walls, install drains	\$30,000
	and add exterior drainage	
2015 - 16	Clean, tuck-point and seal exterior	\$55,000
2016 - 17	Remodel main entrance	\$27,000
2017 - 18	Renovate HVAC system	\$350,000
2017 - 18	Remodel restrooms for ADA	\$35,000
-	TOTAL	\$542,000



GATE HOUSE

Description

Primary Use: Secondary Electrical Distribution Constructed: Original Construction, 1921 Building Area: 767 square feet on 1 floor

Building Usage

100.0% Gross Area: 767 square feet Net Assignable Area: 690 square feet 90.0% Circulation Area: 0 square feet 0.0% Custodial Area: 0 square feet 0.0% Mechanical Area: 0 square feet 0.0% Construction Area: 77 square feet 10.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$140,200

Facility Condition Index: 11% (Poor)



Utility System Infrastructure:

Building infrastructure is in good condition.

Gate House Page 38

Year	Description	Estimate
2012 - 13	Exterior painting including gate wings	\$5,000
2014 - 15	New roof and soffit repairs	\$5,000
2015 - 16	Clean, tuck-point and seal exterior	\$5,000
•	TOTAL	\$15,000



HEALTH CARE CENTER

Description

Primary Use: Health Services Center

Constructed: 1990

Building Area: 2,540 square feet on 1 floor

Building Usage

100.0% Gross Area: 2,540 square feet Net Assignable Area: 1,727 square feet 68.0% 432 square feet Circulation Area: 17.0% Custodial Area: 38 square feet 1.5% Mechanical Area: 89 square feet 3.5% Construction Area: 10.0% 254 square feet

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$419,870

Facility Condition Index: 2% (Good)



Utility System Infrastructure:

Building infrastructure is in good condition.

Health Care Center Page 40

Year	Description	Estimate
2013 - 14	Tie HVAC and fire alarm systems	\$8,000
	to Metasys	
•	TOTAL	\$8,000



HILLSIDE HOUSE

Description

Primary Use: Admissions Center

Constructed: Original Construction, 1920 Building Area: 5,064 square feet on 3 floors

Building Usage

Gross Area:	5,064 square feet	100.0%
Net Assignable Area:	3,444 square feet	68.0%
Circulation Area:	861 square fæt	17.0%
Custodial Area:	76 square feet	1.5%
Mechanical Area:	177 square feet	3.5%
Construction Area:	506 square feet	10.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$1,054,936

Facility Condition Index: 21% (Poor)



Utility System Infrastructure

Building infrastructure is in generally fair condition with no major problems.

The south end of the building was renovated in 2000. The north end was renovated in 2001.

Hillside House Page 42

Year	Description	Estimate
2012 - 13	Repair deck and porches	\$5,000
2013 - 14	Install ADA door hardware	\$8,000
2013 - 14	Install new fire alarm system	\$38,000
2014 - 15	Clean/abate basement	\$9,000
2015 - 16	Clean, tuck-point and seal exterior	\$55,000
2016 - 17	Install electrical power distribution system	\$20,000
2016 - 17	Replace basement windows	\$6,000
2017 - 18	Install ADA accessibility ramp and door opener	\$15,000
2017 - 18	Replace steam boiler with HW heating system	\$65,000
	TOTAL	\$221,000



HOUSING STORAGE BUILDING

Description

Primary Use: Storage Constructed: 1995

Building Area: 2,800 square feet on 1 floor

Building Usage

Gross Area: 2,800 square feet 100% Net Assignable Area: 2,800 square feet 100%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$224,988

Facility Condition Index: 7% (Fair)



Utility System Infrastructure:

Building infrastructure is in fair condition with no major problems.

Housing Storage Building Page 44

Year	Description	Estimate
2012 - 13	Add partial second deck and lighting	\$15,000
	TOTAL	\$15,000



HURON HALL

Description

Primary Use: Student Residence

Constructed: Original Construction, 1901 Building Area: 8,766 square feet on 3 floors

Building Usage

100.0% Gross Area: 8,766 square feet Net Assignable Area: 7,013 square feet 80.0% Circulation Area: 614 square feet 7.0% Custodial Area: 88 square feet 1.0% Mechanical Area: 175 square feet 2.0% Construction Area: 877 square feet 10.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$1,826,141

Facility Condition Index: 4% (Good)



Utility System Infrastructure:

Building infrastructure is in good condition. Building interior was remodeled in 2011.

Huron Hall Page 46

	Year	Description	Estimate
	2012 - 13	Fix basement drainage	\$5,000
	2013 - 14	Repair soffit and fascia	\$10,000
ı	2014 - 15	Install card access entry system	\$10,000
	2016 - 17	Install ADA accessibility ramp	\$35,000
		TOTAL	\$60,000



KJS LIBRARY

Description

Primary Use: Campus Library & Support Spaces Constructed: 1971 original with 1996 addition Building Area: 103,584 square feet on 4 floors

Building Usage

Gross Area: 103,584 square feet 100.0% Net Assignable Area: 76,652 square feet 74.0% Circulation Area: 11,394 square feet 11.0% Custodial Area: 1,554 square feet 1.5% Mechanical Area: 3.5% 3,625 square feet Construction Area: 10.0% 10,358 square feet

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$34,830,297

Facility Condition Index: 2% (Good)



Utility System Infrastructure:

The total building was renovated with a new addition added in 1996; the entire facility is in good condition.

KUS Library Page 48

Year	Description	Estimate
2013 - 14	Replace roof (old side)	\$280,000
2014 - 15	Replace circuit breaker	\$12,000
2014 - 15	Repair substation switch	\$17,000
2014 - 15	Utilities metering	\$21,000
2015 - 16	Install ventilation into computer room off main lobby	\$80,000
2015 - 16	Room 208 A/C	\$20,000
2016 - 17	Replace stone fascia as needed	\$10,000
2016 - 17	A/C into IATV control room	\$30,000
2016 - 17	Window repairs to north side windows	\$25,000
2017 - 18	Clean, tuck-point and seal exterior	\$72,000
2017 - 18	Replace carpeting in main library	\$45,000
2017 - 18	Replace PRV	\$10,000
2017 - 18	Replace carpeting in offices	\$37,000
	TOTAL	\$659,000



LAKER HALL

Description

Primary Use: Student Residence

Constructed: Original Construction, 1920 Building Area: 4,506 square feet on 3 floors

Building Usage

Net Assignable Area: 3,605 square feet 80	
	0.0%
Circulation Area: 315 square feet 7	.0%
Custodial Area: 45 square feet 1	0%
Mechanical Area: 90 square feet 2	2.0%
Construction Area: 451 square feet 10	0.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$938,694

Facility Condition Index: 45% (Poor)



Utility System Infrastructure

Building infrastructure is in fair condition although building interior needs extensive remodeling.

Laker Hall Page 50

Year	Description	Estimate
2012 - 13	Repair chimney	\$5,000
2013 - 14	Clean/abate basement	\$5,000
2014 - 15	Replace basement windows	\$5,000
2015 - 16	Install card access entry system	\$10,000
2016 - 17	Clean, tuck-point and seal exterior	\$55,000
2016 - 17	Replace interior and exterior cellar doors	\$8,000
2017 - 18	Complete renovation	\$300,000
2017 - 18	Install ADA accessibility ramp	\$35,000
	TOTAL	\$423,000



MARQUETTE HALL

Description

Primary Use: Student Residence

Constructed: Original Construction, 1968 Building Area: 15,719 square feet on 2 floors

Building Usage

Gross Area: 15,719 square feet 100.0% Net Assignable Area: 12,575 square feet 80.0% Circulation Area: 7.0% 1,100 square feet Custodial Area: 157 square feet 1.0% Mechanical Area: 2.0% 314 square feet Construction Area: 10.0% 1,572 square feet

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$3,765,784 **Facility Condition Index:** Poor—Building Closed



Utility System Infrastructure:

Building infrastructure is in poor condition. The domestic water system needs to be replaced and building needs remodeling. This building is currently vacant.

Marquette Hall Page 52

Five -Year Capital Improvement Plan

No plans to upgrade this facility - Building Closed

Year			Description	Estimate	
	2012	-	13	Abate all asbestos	\$10,000
	2012	-	13	Demolish building	\$70,000
				TOTAL	\$80,000



MERIDIAN STORAGE BUILDING

Description

Primary Use: Storage Constructed: 1940

Building Area: 736 square feet on 1 floor

Building Usage

Gross Area: 736 square feet 100% Net Assignable Area: 736 square feet 100%

 $\textbf{Mandated Facility Standards:} \ \ N/A$

Replacement Value: (2012 valuation) \$65,882

Facility Condition Index: 8% (Fair)



Utility System Infrastructure:

Building infrastructure is in fair condition with no major problems.

Meridian Storage Building Page 54

Year		Description	Estimate
201	3 - 14	Add electrical service	\$5,000
-		TOTAL	\$5,000



MICHIGAN HALL

Description

Primary Use: Closed in 2012

Constructed: Original Construction, 1920 Building Area: 1,676 square feet on 1 floor

Building Usage

100.0% Gross Area: 1,676 square feet Net Assignable Area: 1,140 square feet 68.0% Circulation Area: 285 square feet 17.0% Custodial Area: 25 square feet 1.5% Mechanical Area: 1.0% 17 square feet Construction Area: 168 square feet 10.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$305,502

Facility Condition Index: 30% (Poor)



Utility System Infrastructure:

Building infrastructure is in poor condition.

Michigan Hall

Year	Description	Estimate
2012 - 13	New fascia, soffit, windows	\$25,000
	and exterior doors	
2012 - 13	Install AC	\$10,000
2012 - 13	Remodel bathrooms	\$8,000
2012 - 13	Landscape improvements	\$5,000
2012 - 13	New flooring	\$5,000
2013 - 14	Replace lighting	\$5,000
2014 - 15	Clean, tuck-point seal exterior	\$15,000
2015 - 16	Renovate electric power distribution	\$12,000
2017 - 18	Replace roof	\$8,000
-	TOTAL	\$93,000



MOLONEY HALL

Description

Primary Use: Student Residence

Constructed: Original Construction, 1969
Building Area: 16,824 square feet on 3 floors

Building Usage

Gross Area: 16,824 square feet 100.0% Net Assignable Area: 13,459 square feet 80.0% Circulation Area: 7.0% 1,178 square feet Custodial Area: 166 square feet 1.0% Mechanical Area: 2.0% 336 square feet Construction Area: 10.0% 1,682 square feet

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$4,030,507

Facility Condition Index: 6% (Fair)



Utility System Infrastructure:

Building infrastructure is in generally fair condition although domestic water system needs replacement and the building needs to be remodeled.

Moloney Hall Page 58

Year	Description	Estimate
2013 - 14	Repair damaged bricks and tuck point	\$5,000
2014 - 15	Replace tub surrounds	\$40,000
2015 - 16	Replace entrance doorways	\$9,000
2015 - 16	Re-core all locking hardware	\$8,000
2016 - 17	Exterior drainage around steam tunnel	\$10,000
2017 - 18	Abate or cover asbestos floor tile and replacement flooring	\$140,000
	TOTAL	\$212,000



NEVEU HALL

Description

Primary Use: Student Residence

Constructed: Original Construction, 1970 Building Area: 13,203 square feet on 3 floors

Building Usage

100.0% Gross Area: 13,203 square feet Net Assignable Area: 10,562 square feet 80.0% Circulation Area: 924 square feet 7.0% Custodial Area: 132 square feet 1.0% Mechanical Area: 264 square feet 2.0% Construction Area: 1,320 square feet 10.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$3,163,028

Facility Condition Index: 6% (Fair)



Utility System Infrastructure:

Building infrastructure is in generally fair condition although building interior needs to be remodeled.

Neveu Hall Page 60

Year	Description	Estimate
2013 - 14	Repair damaged bricks and tuck point	\$5,000
2014 - 15	Replace entrance doors	\$10,000
2014 - 15	Re-core all locking hardware	\$8,000
2016 - 17	Exterior drainage around steam tunnel	\$10,000
2017 - 18	Abate or cover asbestos floor tile and replacement flooring	\$140,000
	TOTAL	\$173,000



NORRIS CENTER

Description

Primary Use: Classrooms, Gymnasium, Pool, Ice Arena,

& related athletic functions and support space

Constructed: 1974 w/ addition to Ice Arena in 1995 Building Area: 209,928 square feet on 3 floors

Building Usage

Gross Area: 209,928 square feet 100.0% Net Assignable Area: 157,446 square feet 75.0% Circulation Area: 27,291 square feet 13.0% 1.5% **Custodial Area:** 3,149 square feet Mechanical Area: 5,248 square feet 2.5% Construction Area: 16,794 square feet 8.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$22,758,733

Facility Condition Index: 9% (Fair)



Utility System Infrastructure:

Building is in generally good condition although a new fire alarm system and a pool dehumidification system are needed.

Norris Center Page 62

Year	Description	Estimate
2012 - 13	Pool pit pump on generator	\$5,000
2012 - 13	Replace carpet in CJ/FS offices	\$5,000
2012 - 13	Replace celing tiles in pool	\$8,000
2013 - 14	Renovate sauna in men's locker room	\$10,000
2013 - 14	Replace tennis courts	\$60,000
2013 - 14	Replace air conditioners - AHU 1	\$30,000
2013 - 14	Clean, tuck-point and seal exterior	\$125,000
2013 - 14	Repair/resurface dance floor	\$18,000
2013 - 14	New rink roof	\$350,000
2013 - 14	Replace carpet in 2nd floor classrooms	\$8,000
2014 - 15	Replace basement electrical	\$60,000
2014 - 14	Abate & refinish tennis court light poles	\$13,000
2014 - 15	Rink dehumidification	\$70,000
2014 - 15	Replace domestic water pipes in north end	\$70,000
2014 - 15	Replace carpeting first floor	\$25,000
2014 - 15	Renovate gym HVAC system to add humidity control	\$60,000
2015 - 16	New roof on lobby and entrances	\$70,000
2015 - 16	Refurbish rifle range HVAC system	\$28,000
2015 - 16	Repair electrical to tennis courts	\$10,000
2015 - 16	Replace electrical lines and breakers	\$25,000
2016 - 17	Replace fire alarm system	\$170,000
2016 - 17	Renovate pool lap pool drain system	\$60,000
2016 - 17	New storage garage (30x40x10)	\$20,000
2016 - 17	Pipe insulation for restrooms	\$45,000
2017 - 18	Emergency generator	\$350,000
2017 - 18	Pool dehumidification	\$300,000
	TOTAL	\$1,995,000



ONTARIO HALL

Description

Primary Use: Student Residence

Constructed: 1920 with 1994 renovation Building Area: 7,752 square feet on 4 floors

Building Usage

Gross Area: 7,752 square feet 100.0% Net Assignable Area: 6,202 square feet 80.0% Circulation Area: 543 square feet 7.0% **Custodial Area:** 78 square feet 1.0% Mechanical Area: 2.0% 155 square feet Construction Area: 775 square feet 10.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$1,614902

Facility Condition Index: 7% (Fair)



Utility System Infrastructure:

Building infrastructure is in good condition with no major problems.

Ontario Hall Page 64

Year	Description	Estimate
2012 - 13	Replace carpet on 2nd floor	\$5,000
2013 - 14	Clean, tuck-point and seal exterior	\$50,000
2013 - 14	Replace basement windows	\$8,000
2014 - 15	Install card access system	\$10,000
2015 - 16	Clean/abate basements	\$10,000
2017 - 18	Replace interior and exterior cellar doors	\$8,000
	TOTAL	\$91,000



OSBORN HALL

Description

Primary Use: Student Residence

Constructed: Original Construction, 1967 Building Area: 47,476 square feet on 4 floors

Building Usage

Gross Area: 47,476 square feet 100.0% Net Assignable Area: 37,981 square feet 80.0% Circulation Area: 3,323 square feet 7.0% Custodial Area: 475 square feet 1.0% Mechanical Area: 2.0% 950 square feet Construction Area: 4,748 square feet 10.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$11,373,774

Facility Condition Index: 23% (Poor)



Utility System Infrastructure:

Building is structurally in fair condition but needs new heating and domestic water systems.

Osborn Hall Page 66

	Year	Description	Estimate
	2012 - 13	Replace roof, trim, soffit and fascia	\$200,000
	2012 - 13	Install carpet in large side rooms	\$75,000
	2013 - 14	Install card access entry system	\$25,000
	2013 - 14	Energy management system control of RTU's	\$12,000
	2014 - 15	Clean, tuck-point and seal exterior	\$75,000
	2014 - 15	Replace domestic hot water system	\$180,000
	2015 - 16	Reconfigure heating system	\$800,000
	2015 - 16	New electrical power feed / fix water infiltration	\$350,000
	2016 - 17	AHU replacements	\$350,000
	2017 - 18	Add electrical power for rooms	\$180,000
	2017 - 18	Fire suppression system	\$350,000
		TOTAL	\$2,597,000



PIANOSI MAINTENANCE BUILDING

Description

Primary Use: Campus Maintenance Shops,

Office & Storage Building

Constructed: Original Construction, 1977 Building Area: 35,464 square feet on 1 floor

w/attached warehouse

Building Usage

Gross Area: 35,464 square feet 100.0%

Net Assignable Area: 24,116 square feet 68.0%

Circulation Area: 6,029 square feet 17.0%

Custodial Area: 532 square feet 1.5%

Mechanical Area: 1,241 square feet 3.5%

Construction Area: 3,546 square feet 10.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$4,966,992

Facility Condition Index: 8% (Fair)



Utility System Infrastructure

The building is in fair condition.

Planosi Maintenance Building Page 68

Year	Description	Estimate
2012 - 13	Replace loading dock door	\$6,000
2013 - 14	Emergency generator	\$70,000
2013 - 14	Install fire suppression system	\$80,000
2014 - 15	Metering	\$18,000
2014 - 15	Replace carpeting	\$20,000
2015 - 16	Install A/C in offices	\$20,000
2016 - 17	Replace office roof	\$80,000
2017 - 18	Storage building	\$100,000
•	TOTAL	\$394,000



PRESIDENT'S HOUSE

Description

Primary Use: University President Residence Constructed: Original Construction, 1920 Building Area: 7,027square feet on 4 floors

Building Usage

Gross Area: 7,027 square feet 100.0% Net Assignable Area: 5,762 square feet 82.0% Circulation Area: 351 square feet 5.0% Custodial Area: 70 square feet 1.0% Mechanical Area: 2.0% 141 square feet 703 square feet Construction Area: 10.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$1,463,870

Facility Condition Index: 37% (Poor)



Utility System Infrastructure:

Building infrastructure is in fair condition with no major problems. However, this facility is circa 1920 and needs extensive work to be brought into the 21st century.

.

President's House Page 70

Year	Description	Estimate
2012 - 13	Repair chimneys	\$16,000
2013 - 14	Replace basement windows	\$8,000
2013 - 14	New windows	\$50,000
2013 - 14	Replace basement cellar doors	\$5,000
2014 - 15	Metering	\$14,000
2014 - 15	Convert heating system from	\$250,000
	steam to HW	
2015 - 16	Electrical upgrades	\$25,000
2015 - 16	Clean, tuck-point and seal exterior	\$55,000
2015 - 16	Kitchen remodel	\$20,000
2016 - 17	New garage	\$25,000
2016 - 17	Clean and abate basement	\$10,000
2016 - 17	Dewater basement	\$10,000
2017 - 18	Relocate laundry room	\$10,000
2017 - 18	Fire suppression system	\$40,000
	TOTAL	\$538,000



ROW HOUSING STORAGE BUILDING

Description

Primary Use: Storage Constructed: 1999

Building Area: 1,920 square feet on 1 floor

Building Usage

Gross Area: 1,920 square feet 100% Net Assignable Area: 1,920 square feet 100%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$135,409

Facility Condition Index: 7% (Fair)



Utility System Infrastructure:

Building infrastructure is in fair condition with no major problems.

Row Housing Storage Building Page 72

Year	Description	Estimate
2016 - 17	Re-shingle roof	\$10,000
-	TOTAL	\$10,000



RYAN HOUSE

Description

Primary Use: Student Residence

Constructed: Original Construction, 1920 Building Area: 3,456 square feet on 3 floors


Building Usage

Gross Area: 3,456 square feet 100.0% Net Assignable Area: 2,419 square feet 70.0% Circulation Area: 588 square feet 17.0% Custodial Area: 35 square feet 1.0% Mechanical Area: 69 square feet 2.0% Construction Area: 346 square feet 10.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$719,957

Facility Condition Index: 57% (Poor)



Utility System Infrastructure

Building infrastructure is in fair condition although building interior needs to be remodeled.

Ryan House Page 74

Year	Description	Estimate
2012 - 13	Repair east porch	\$6,000
2013 - 14	Renovate HW heating system	\$60,000
2013 - 14	Replace basement windows	\$8,000
2014 - 15	Install card access entry system	\$10,000
2014 - 15	Abate asbestos floor tiles and replacement flooring	\$20,000
2015 - 16	Clean/abate basement	\$10,000
2015 - 16	Clean, tuck-point and seal exterior	\$55,000
2017 - 18	Add electrical power to each room	\$40,000
2017 - 18	Remodel interior	\$200,000
•	TOTAL	\$409,000



SOUTH HALL

Description

Primary Use: Student Support & Classroom

Space

Constructed: 1920 w/1946 renovation Building Area: 33,812 square feet on 3 floors

Building Usage

Gross Area: 33,812 square feet 100.0% Net Assignable Area: 22,654 square feet 67.0% 16.0% Circulation Area: 5,410 square feet **Custodial Area:** 338 square feet 1.0% Mechanical Area: 4.0% 1,352 square feet Construction Area: 4,057 square feet 12.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$2,980,771

Facility Condition Index: +100% (Poor)



Utility System Infrastructure:

Building was vacated, August 2005. Planning has begun for complete renovation of South Hall.

South Hall Page 76

Five -Year Capital Improvement Plan

Awaiting Capital Project for complete renovation

Year		Estimate
	Complete Renovation	\$12,000,000
	(Not included in Summaries)	
•	TOTAL	\$12,000,000



STUDENT ACTIVITIES CENTER

Description

Primary Use: Student Intramural Sports /

Physical Activity Center

Constructed: Original Construction, 1999 Building Area: 69,095 square feet on 1 floor

Building Usage

Gross Area: 69,095 square feet 100.0%

Net Assignable Area: 46,985 square feet 68.0%

Circulation Area: 11,746 square feet 17.0%

Custodial Area: 1,036 square feet 1.5%

Mechanical Area: 2,418 square feet 3.5%

Construction Area: 6,910 square feet 10.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$10,795,443

Facility Condition Index: 2% (Good)



Utility System Infrastructure

This building is a newer structure and in good condition.

Student Activities Center Page 78

Year	Description	Estimate
2012 - 13	Fix exterior doors	\$10,000
2013 - 14	Add electrical power for events	\$20,000
2014 - 15	Metering	\$14,000
2015 - 16	Replace curtains	\$50,000
2017 - 18	Add second level for exercise equipment	\$100,000
•	TOTAL	\$194,000



STUDENT VILLAGE

Description

Primary Use: Student Residence

Constructed: Original Construction, 1970 Building Area: 48,192 square feet on 4 floors

Building Usage

Gross Area: 48,192 square feet 100.0% Net Assignable Area: 32,771 square feet 68.0% 8,193 square feet Circulation Area: 17.0% Custodial Area: 723 square feet 1.5% Mechanical Area: 3.5% 1,687square feet Construction Area: 4,819 square feet 10.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$11,545,305

Facility Condition Index: 7% (Fair)



Utility System Infrastructure:

Building infrastructure is in good condition although building interiors need to be remodeled.

Student Village Page 80

Year	Description	Estimate
2012 - 13	Address mechanical room ventilation	\$5,000
2012 - 13	Replace five lower level doors and frames	\$12,000
2013 - 14	ADA upgrade to apartment B2	\$10,000
2013 - 14	Install card access entry system	\$36,000
2013 - 14	Replace primary transformer and switch gear	\$25,000
2014 - 15	Clean, tuck-point and seal exterior	\$80,000
2014 - 15	Clean and abate basement	\$20,000
2014 - 15	Recore all locking hardware	\$12,000
2015 - 16	Replace apartment doors	\$40,000
2015 - 16	Interior renovations in Tower A	\$55,000
2015 - 16	Abate and replace floor tile in A tower	\$35,000
2015 - 16	Install new stair tread	\$10,000
2016 - 17	Add electrical to each room	\$34,000
2016 - 17	Interior renovations in Tower B	\$55,000
2016 - 17	Abate and replace floor tile in B tower	\$35,000
2017 - 18	Abate and replace floor tile in C tower	\$35,000
2017 - 18	Abate and replace floor tile in D tower	\$35,000
2017 - 18	Replace water and sewer pipes in all towers	\$40,000
2017 - 18	Fire suppression system	\$200,000
_	TOTAL	\$774,000



TOWNHOUSES

Description

Primary Use: Student Residence

Constructed: Original Construction, 1974 Building Area: 29,665square feet on 2 floors

Building Usage

Gross Area: 29,665 square feet 100.0% Net Assignable Area: 22,249 square feet 75.0% Circulation Area: 2,967square feet 10.0% Custodial Area: 445 square feet 1.5% Mechanical Area: 1,038 square feet 3.5% Construction Area: 10.0% 2,967 square feet

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$7,106,811

Facility Condition Index: 16% (Poor)



Utility System Infrastructure:

Building infrastructure is in generally fair condition although domestic water system needs replacement. Exterior needs to be painted. Townhouses need to be remodeled.

Townhouses Page 82

Year	Description	Estimate
2012 - 13	Replace 2nd floor carpet	\$48,000
2012 - 13	Replace roof	\$75,000
2013 - 14	Phase 1 - Interior renovations	\$125,000
2013 - 14	Install card access system	\$75,000
2014 - 15	Re-core all locks with new hardware	\$75,000
2014 - 15	Clean and abate mechanical room	\$5,000
2014 - 15	Phase 2 - Interior renovations	\$125,000
2015 - 16	Clean, tuck-point and seal exterior	\$30,000
2015 - 16	Phase 3 - Interior renovations	\$125,000
2017 - 18	Fire suppression system	\$350,000
2017 - 18	Replace domestic water lines	\$93,000
-	TOTAL	\$1,126,000



Youngs House

Description

Primary Use: Housing Director Residence

Constructed: 1959

Building Area: 1,426 square feet on 1 floor

Building Usage

Gross Area: 1,426 square feet 100%

Net Assignable Area: 1,332 square feet 93.5%

Custodial Area: 22 square feet 1.5%

Mechanical Area: 72 square feet 5.0%

Mandated Facility Standards: N/A

Replacement Value: (2012 valuation) \$50,564

Facility Condition Index: 9% (Fair)



Utility System Infrastructure:

Building infrastructure is in fair condition with no major problems.

Youngs House Page 84

Year	Description	Estimate
2014 - 15	Replace carpet	\$5,000
<u>.</u>	TOTAL	\$5.000



Five-Year Facility Assessment Infrastructure

Infrastructure Page 85

Year	Description	Estimate
2012 - 13	Primary electric line replacement (2/yr)	\$50,000
2012 - 13	Replace sidewalks	\$20,000
2012 - 13	Electrical switch gear cleaning & testing	\$90,000
2013 - 14	Replace sidewalks	\$50,000
2013 - 14	Primary electric line replacement (2/yr)	\$50,000
2013 - 14	Repair and dewater electric vaults	\$30,000
2013 - 14	Parking lot upkeep, repair	\$70,000
	and replacement	
2013 - 14	Campus road upkeep, repair	\$40,000
2013 - 13	and replacement	
2013 - 14	Sanitary / storm sewer repairs	\$12,000
2013 - 14	IT communication line maintenance	\$50,000
2013 - 14	Fire hydrant and water line upgrades	\$25,000
2014 - 15	Electrical switch gear cleaning & testing	\$15,000
2014 - 15	Replace sidewalks	\$50,000
2014 - 15	Replace Row House water main	\$200,000
2014 - 15	Primary electric line replacement (2/yr)	\$50,000
2014 - 15	Repair and dewater electric vaults	\$30,000
2014 - 15	Parking lot upkeep, repair	\$70,000
	and replacement	
2014 - 15	Campus road upkeep, repair	\$40,000
	and replacement	•
2014 - 15	Sanitary / storm sewer repairs	\$12,000
2014 - 15	IT communication line upgrade	\$50,000
2014 - 15	Fire hydrant and water line upgrades	\$25,000
2015 - 16	Replace sidewalks	\$50,000
2015 - 16	Primary electric line replacement (2/yr)	\$50,000
2015 - 16	Repair and dewater electric vaults	\$30,000
2015 - 16	Parking lot upkeep, repair	\$70,000
0045 40	and replacement	# 40.000
2015 - 16	Campus road upkeep, repair	\$40,000
0015 10	and replacement	#10.000
2015 - 16	Sanitary / storm sewer repairs	\$12,000
2015 - 16	IT communication line upgrade	\$50,000
2015 - 16	Fire hydrant and water line upgrades	\$25,000
Infra	structure continued on next page	

Infrastructure Page 86

2016 - 17 Replace sidewalks	\$50,000
2016 - 17 Primary electric line replacement (2/yr)	\$50,000
2016 - 17 Parking lot upkeep, repair	\$70,000
and replacement	
2016 - 17 Campus road upkeep, repair	\$20,000
and replacement	
2016 - 17 Sanitary / storm sewer repairs	\$12,000
2016 - 17 IT communication line upgrade	\$50,000
2016 - 17 Fire hydrant and water line upgrades	\$25,000
2017 - 18 Replace sidewalks	\$50,000
2017 - 18 Primary electric line replacement (2/yr)	\$50,000
2017 - 18 Parking lot upkeep, repair	\$70,000
2017 - 18 and replacement	
2017 - 18 Campus road upkeep, repair	\$20,000
2017 - 18 and replacement	
2017 - 18 Sanitary / storm sewer repairs	\$12,000
2017 - 18 IT communication line upgrade	\$50,000
2017 - 18 Fire hydrant and water line upgrades	\$25,000
TOTAL	51,910,000



Five-Year Facility Assessment Summary by Year

2012-13 Capital Improvement Summary

Building	Estimate
Administration Building	\$32,500
Alumni House	\$36,000
Aquatic Research Laboratory	\$0
Arts Center	\$10,000
Barnes & Noble at LSSU	\$0
Brady Hall	\$40,000
Brown Hall	\$95,000
CASET Building	\$80,000
Central Heating Plant	\$15,000
Chippewa Hall	\$5,000
Cisler Center	\$53,000
Crawford Hall of Science	\$0
East Hall	\$0
Easterday House	\$0
Erie Hall	\$8,000
Eskoonwid Endaad	\$13,000
Fire Science Building	\$0
Fletcher Center	\$10,000
Gate House	\$5,000
Health Care Center	\$0
Hillside House	\$5,000
Housing Storage Building	\$15,000
Huron Hall	\$5,000
KJS Library	\$0
Laker Hall	\$5,000
Marquette Hall	\$80,000
Meridian Storage Building	\$0
Michigan Hall	\$53,000
Moloney Hall	\$0
Neveu Hall	\$0
Norris Center	\$18,000
Ontario Hall	\$5,000
Osborn Hall	\$275,000
Pianosi Maintenance Building	\$6,000
President's House	\$16,000
Row Housing Storage Building	\$0
Ryan House	\$6,000
South Hall	\$0
Student Activity Center	\$10,000
Student Village	\$17,000
Townhouses	\$123,000
Youngs House	\$0
Infrastructure	\$160,000
TOTAL	\$1,201,500

2013-14 Capital Improvement Summary

Building	Estimate
Administration Building	\$81,000
Alumni House	\$12,000
Aquatic Research Laboratory	\$0
Arts Center	\$0
Barnes & Noble at LSSU	\$0
Brady Hall	\$57,000
Brown Hall	\$18,000
CASET Building	\$85,000
Central Heating Plant	\$158,000
Chippewa Hall	\$24,000
Cisler Center	\$77,000
Crawford Hall of Science	\$15,000
East Hall	\$0
Easterday House	\$35,000
Erie Hall	\$23,000
Eskoonwid Endaad	\$12,000
Fire Science Building	\$0
Fletcher Center	\$35,000
Gate House	\$0
Health Care Center	\$8,000
Hillside House	\$46,000
Housing Storage Building	\$0
Huron Hall	\$10,000
KJS Library	\$280,000
Laker Hall	\$5,000
Marquette Hall	\$0
Meridian Storage Building	\$5,000
Michigan Hall	\$5,000
Moloney Hall	\$5,000
Neveu Hall	\$5,000
Norris Center	\$601,000
Ontario Hall	\$58,000
Osborn Hall	\$37,000
Pianosi Maintenance Building	\$150,000
President's House	\$63,000
Row Housing Storage Building	\$0
Ryan House	\$68,000
South Hall	\$0
Student Activity Center	\$20,000
Student Village	\$71,000
Townhouses	\$200,000
Youngs House	\$0
Infrastructure	\$327,000
TOTAL	\$2,596,000

2014-15 Capital Improvement Summary

Building	Estimate
Administration Building	\$187,500
Alumni House	\$72,000
Aquatic Research Laboratory	\$0
Arts Center	\$17,000
Barnes & Noble at LSSU	\$20,000
Brady Hall	\$217,000
Brown Hall	\$5,000
CASET Building	\$102,000
Central Heating Plant	\$0
Chippewa Hall	\$14,000
Cisler Center	\$30,000
Crawford Hall of Science	\$10,000
East Hall	\$0
Easterday House	\$20,000
Erie Hall	\$56,000
Eskoonwid Endaad	\$35,000
Fire Science Building	\$0
Fletcher Center	\$30,000
Gate House	\$5,000
Health Care Center	\$0
Hillside House	\$9,000
Housing Storage Building	\$0
Huron Hall	\$10,000
KJS Library	\$50,000
Laker Hall	\$5,000
Marquette Hall	\$0
Meridian Storage Building	\$0
Michigan Hall	\$15,000
Moloney Hall	\$40,000
Neveu Hall	\$18,000
Norris Center	\$298,000
Ontario Hall	\$10,000
Osborn Hall	\$255,000
Pianosi Maintenance Building	\$38,000
President's House	\$264,000
Row Housing Storage Building	\$0
Ryan House	\$30,000
South Hall	\$0
Student Activity Center	\$14,000
Student Village	\$112,000
Townhouses	\$205,000
Youngs House	\$5,000
Infrastructure	\$542,000
TOTAL	\$2,740,500

2015-16 Capital Improvement Summary

Building	Estimate
Administration Building	\$84,000
Alumni House	\$63,000
Aquatic Research Laboratory	\$0
Arts Center	\$0
Barnes & Noble at LSSU	\$31,000
Brady Hall	\$210,000
Brown Hall	\$26,000
CASET Building	\$70,000
Central Heating Plant	\$100,000
Chippewa Hall	\$55,000
Cisler Center	\$105,000
Crawford Hall of Science	\$40,000
East Hall	\$20,000
Easterday House	\$47,000
Erie Hall	\$410,000
Eskoonwid Endaad	\$51,000
Fire Science Building	\$30,000
Fletcher Center	\$55,000
Gate House	\$5,000
Health Care Center	\$0
Hillside House	\$55,000
Housing Storage Building	\$0
Huron Hall	\$0
KJS Library	\$100,000
Laker Hall	\$10,000
Marquette Hall	\$0
Meridian Storage Building	\$0
Michigan Hall	\$12,000
Moloney Hall	\$17,000
Neveu Hall	\$0
Norris Center	\$133,000
Ontario Hall	\$10,000
Osborn Hall	\$1,150,000
Pianosi Maintenance Building	\$20,000
President's House	\$100,000
Row Housing Storage Building	\$0
Ryan House	\$65,000
South Hall	\$0
Student Activity Center	\$50,000
Student Village	\$140,000
Townhouses	\$155,000
Youngs House	\$0
Infrastructure	\$327,000
TOTAL	\$3,746,000

2016-17 Capital Improvement Summary

Building	Estimate
Administration Building	\$500,000
Alumni House	\$65,000
Aquatic Research Laboratory	\$0
Arts Center	\$8,000
Barnes & Noble at LSSU	\$40,000
Brady Hall	\$675,000
Brown Hall	\$10,000
CASET Building	\$92,000
Central Heating Plant	\$50,000
Chippewa Hall	\$17,000
Cisler Center	\$150,000
Crawford Hall of Science	\$60,000
East Hall	\$0
Easterday House	\$360,000
Erie Hall	\$35,000
Eskoonwid Endaad	\$55,000
Fire Science Building	\$0
Fletcher Center	\$27,000
Gate House	\$0
Health Care Center	\$0
Hillside House	\$26,000
Housing Storage Building	\$0
Huron Hall	\$35,000
KJS Library	\$65,000
Laker Hall	\$63,000
Marquette Hall	\$0
Meridian Storage Building	\$0
Michigan Hall	\$0
Moloney Hall	\$10,000
Neveu Hall	\$10,000
Norris Center	\$295,000
Ontario Hall	\$0
Osborn Hall	\$350,000
Pianosi Maintenance Building	\$80,000
President's House	\$45,000
Row Housing Storage Building	\$10,000
Ryan House	\$0
South Hall	\$0
Student Activity Center	\$0
Student Village	\$124,000
Townhouses	\$0
Youngs House	\$0
Infrastructure	\$277,000
TOTAL	\$3,534,000
. 5 17 12	ψο,οο 1,οοο

2017-18 Capital Improvement Summary

D """		F :: .
Building	D. Helio e	Estimate
Administration		\$150,000
Alumni House		\$236,000
Arts Center	arch Laboratory	\$0 \$0
Barnes & Nob	lo at LCCLL	•
	le at LSSU	\$40,000
Brady Hall		\$190,000
Brown Hall	-	\$70,000
CASET Buildir	•	\$250,000
Central Heatin	*	\$0
Chippewa Hal		\$35,000
Cisler Center		\$395,000
Crawford Hall	of Science	\$0
East Hall		\$0
Easterday Hou	use	\$70,000
Erie Hall		\$5,000
Eskoonwid En		\$60,000
Fire Science E		\$0
Fletcher Center	er	\$385,000
Gate House		\$0
Health Care C	enter	\$0
Hillside House		\$80,000
Housing Stora	ge Building	\$0
Huron Hall		\$0
KJS Library		\$164,000
Laker Hall		\$335,000
Marquette Hal		\$0
Meridian Stora	ige Building	\$0
Michigan Hall		\$8,000
Moloney Hall		\$140,000
Neveu Hall		\$140,000
Norris Center		\$650,000
Ontario Hall		\$8,000
Osborn Hall		\$530,000
Pianosi Mainte	enance Building	\$100,000
President's Ho		\$50,000
Row Housing	Storage Building	\$0
Ryan House	<u> </u>	\$240,000
South Hall		\$0
Student Activit	v Center	\$100,000
Student Village	•	\$310,000
Townhouses		\$443,000
Youngs House		\$0
Infrastructure		\$277,000
	TOTAL	\$5,461,000
	. 3 17 (2	ψο, το 1,000
	Auxiliary Building Total	\$9,388,000
	General Fund Building Total	\$9,891,000
	6 Year Grand Total	\$19,279,000
	o rour drand rotal	Ψ13,273,000